## Findings for walkthrough Glenwood Middle School: July 6th, 2023 (WXXGMS2023000470)

| Tracking Number  | Finding Type   | Comments  | Location                            | Assigned To    | Closed |
|------------------|--|---|-------------------------------------|----------------|--------|
| FXXGMS20230023B4 | Stained/damaged tiles  | Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile. | Outside Room 30                     | custodial      | Yes    |
|                  | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | The return vent is visibly dirty and requires dusting/cleaning.   | Outside of 34 Near<br>Exterior Door | custodial      | Yes    |
| FXXGMS20230023B6 | Stained/damaged tiles  | Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile. | Above Locker 417                    | custodial      | Yes    |
| FXXGMS20230023B7 | Tight seal on ceiling tiles  | Hole in corner of tile. Tile is to be replaced.   | Outside Room 12                     | custodial      | Yes    |
|                  | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Fan Coil Unit 5.13 (ceiling) is visibley dusty and requires cleaning.   | Computer Lab                        | custodial      | Yes    |
| FXXGMS20230023B9 | 18" Of Clearance from Ceiling  | Some objects stored very close to sprinkler heads.  | Media Storage                       | administration | Yes    |
| FXXGMS20230023BA | General Cleanliness/Dust   | Piano dusty and requiers cleaning.  | Room 37                             | custodial      | Yes    |
| FXXGMS20230023BB | Stained/damaged tiles  | Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile. | Outside Room 38                     | custodial      | Yes    |
| FXXGMS20230023BC | Stained/damaged tiles  | Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile. | Both Art Storage Closets            | custodial      | Yes    |
| FXXGMS20230023BD | Tight seal on ceiling tiles  | Broken tile is to be replaced.  | Weight Room                         | custodial      | Yes    |
| FXXGMS20230023BE | Stained/damaged tiles  | Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile. | Outside of Gym/Staff<br>Lounge      | custodial      | Yes    |

| <b>Tracking Number</b> | Finding Type   | Comments  | Location   | <b>Assigned To</b> | Closed |
|------------------------|--|---|--|--------------------|--------|
| FXXGMS20230023BF       | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | The return vent is visibly dirty and requires dusting/cleaning.   | Outside Gym/Media  | custodial          | Yes    |
| FXXGMS20230023C0       | Uncomfortable temperature  | The supply diffuser has condensation on it and appears to be overcooling.   | Outside Boiler Room  | building           | Yes    |
| FXXGMS20230023C1       | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)                | A refrigerator and microwave was observed. If not serving an educational purpose, these items are recommended to be removed to improve energy conservation. | Classroom 12   | administration     | Yes    |
| FXXGMS20230023F7       | Penetrations not sealed  | An "L" bracket at the inside corner of the building appears to be coming loose/un-caulked.  | Exterior - Behind Tech<br>Ed/Next to Art                     | building           | Yes    |
| FXXGMS20230023F8       | Penetrations not sealed  | Brick missing.  | Exterior - Back Left<br>Corner (when viewing<br>from street) | building           | Yes    |
| FXXGMS20230023F9       | Door and window caulking and weather stripping   | The caulk around the relief vent for the boiler room is deteriorating.  | Exterior   | building           | Yes    |
| FXXGMS20230023FA       | Miscellaneous finding  | Mandatory lead signage on the exterior hose bib has been removed/vandalized.  | Exterior   | building           | Yes    |