

Findings for walkthrough Ducketts Lane Elementary School: August 14th, 2023 (WXDLES202300048E)

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|-------------------------------|--|-------------------------|----------------|--------|
| FXDLES2023002577 | 18" Of Clearance from Ceiling | Miscellaneous items stored on top of shelves less than 18 inches from the ceiling. Remove/reconfigure to comply with Fire Code. | Classroom # A135 | administration | Yes |
| FXDLES2023002578 | 18" Of Clearance from Ceiling | Miscellaneous items stored less than 18 inches from the ceiling. Remove/reconfigure to comply with Fire Code. | Computer B118 | administration | Yes |
| FXDLES2023002579 | 18" Of Clearance from Ceiling | Miscellaneous items stored less than 18 inches from the ceiling. Remove/reconfigure to comply with Fire Code. | Extended Learning C127 | administration | Yes |
| FXDLES202300257A | Miscellaneous finding | Lights do not appear to be working. Place a work order if one is not already in place. | Custodial Storage C114A | custodial | Yes |
| FXDLES202300257B | Miscellaneous finding | Space temperature 72.2. deg. overcooling. The temperature are several degrees below the standard of HCPSS Guidelines for Energy Conservation setting of 76 deg. for cooling mode. Building Maintenance to review the HVAC controls and temperature settings for the school to improve energy conservation. | Staff Lounge | building | Yes |
| FXDLES2023002591 | Miscellaneous finding | Majority of the areas in the building are being overcooled into the low 70 deg. The temperature are several degrees below the standard of HCPSS Guidelines for Energy Conservation setting of 76 deg. for cooling mode. Building Maintenance to review the HVAC controls and temperature settings for the school to improve energy conservation. | Throughout the Building | building | Yes |