# Findings for walkthrough Hammond High School: January 24th, 2019 (WXHAHS2019000113)

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|---|---|---|---|---|---|
| FXHAHS201900077F | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Supply diffusers rusty, in general throughout. Place work order for Building Services to re-paint or replace. | General | building | Yes |
| FXHAHS2019000781 | Tight seal on ceiling tiles | | 604 | custodial | Yes |
| FXHAHS2019000782 | Elevated moisture per moisture meter | | 604 | environmental | Yes |
| FXHAHS2019000783 | Tight seal on ceiling tiles | | Kitchen Office | custodial | Yes |
| FXHAHS2019000784 | Plumbing fixture leaking/draining slowly | | 609 | building | Yes |
| FXHAHS2019000785 | Elevated moisture per moisture meter | | 610 | environmental | Yes |
| FXHAHS2019000786 | Tight seal on ceiling tiles | | 611 | custodial | Yes |
| FXHAHS2019000787 | Air freshener/essential oils | | Custodial Locker Room | administration | Yes |
| FXHAHS2019000788 | Miscellaneous finding | Missing light panel | Science prep | | No |
| FXHAHS2019000789 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | | Band Office | administration | Yes |
| FXHAHS201900078A | General Cleanliness/Dust | | Band Office | administration | Yes |
| FXHAHS201900078B | Tight seal on ceiling tiles | Hole in tile | Band Office | custodial | Yes |
| FXHAHS201900078D | Chemicals are capped | Storage Height (fire code) | Band Storage | administration | Yes |
| FXHAHS201900078F | Tight seal on ceiling tiles | | 510 | custodial | Yes |
| FXHAHS2019000790 | Tight seal on ceiling tiles | Stained tile | 213 | custodial | Yes |
| FXHAHS2019000791 | Uncomfortable temperature | Usally hot | Media | building | Yes |
| FXHAHS2019000792 | Elevated moisture per moisture meter | | 522 | environmental | Yes |
| FXHAHS2019000793 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Both electrical rooms across from 103 | Electrical Room across from103 | administration | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|---|---|---|---|---|---|
| FXHAHS2019000794 | Elevated moisture per moisture meter | | 521 | environmental | Yes |
| FXHAHS2019000796 | Tight seal on ceiling tiles | | 304 | custodial | Yes |
| FXHAHS2019000797 | Tight seal on ceiling tiles | | 304 closet | custodial | Yes |
| FXHAHS2019000798 | Miscellaneous finding | Stagecraft - Suspect mold growth on insulation. Office of environment will submit a work order. | auditorium | environmental | Yes |
| FXHAHS201900079A | Elevated moisture per moisture meter | | 518 | environmental | Yes |
| FXHAHS201900079B | Miscellaneous finding | Stagecraft - material in front of door blocking. Wood on floor with nails sticking up - Extremely unsafe. | auditorium | | No |
| FXHAHS201900079C | Tight seal on ceiling tiles | | 303 storage | custodial | Yes |
| FXHAHS201900079E | Tight seal on ceiling tiles | | 303 office | custodial | Yes |
| FXHAHS201900079F | Windows/Doors open | | 505 | building | Yes |
| FXHAHS20190007A0 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | 302 | administration | Yes |
| FXHAHS20190007A1 | Tight seal on ceiling tiles | | 302 | custodial | Yes |
| FXHAHS20190007A2 | General Cleanliness/Dust | | 302 | custodial | Yes |
| FXHAHS20190007A3 | Tight seal on ceiling tiles | | 516 | custodial | Yes |
| FXHAHS20190007A4 | Tight seal on ceiling tiles | | 501 | custodial | Yes |
| FXHAHS20190007A5 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | 501 | administration | Yes |
| FXHAHS20190007A6 | Elevated moisture per moisture meter | | 226 | environmental | Yes |
| FXHAHS20190007A7 | Tight seal on ceiling tiles | | 228 | custodial | Yes |
| FXHAHS20190007A8 | Tight seal on ceiling tiles | | Boys Team Room | custodial | Yes |
| FXHAHS20190007A9 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | Large amount of furniture in storage closet, should be removed to prevent summer mold growth issues. If the items are not being used, discard. | Boys Locker | administration | Yes |
| FXHAHS20190007AB | Tight seal on ceiling tiles | Boys Locker Room office | Boys Locker | custodial | Yes |
| FXHAHS20190007AD | Elevated moisture per moisture meter | | 230 | environmental | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|---|---|---|---|---|---|
| FXHAHS20190007AE | Plumbing fixture leaking/draining slowly | | 230 | building | Yes |
| FXHAHS20190007AF | Elevated moisture per moisture meter | | Art closet | environmental | Yes |
| FXHAHS20190007B0 | Tight seal on ceiling tiles | Missing tile, water damaged tiles | 217 | custodial | Yes |
| FXHAHS20190007B1 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | 607 | administration | Yes |
| FXHAHS20190007B2 | Tight seal on ceiling tiles | Missing tile | Training Room Boys Locker Room | custodial | Yes |
| FXHAHS20190007B6 | Plumbing fixture leaking/draining slowly | | Guidance sink | custodial | Yes |