

Findings for walkthrough Patuxent Valley Middle School: July 26th, 2023

(WXPVMS202300047B)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXPVMS202300245A	Miscellaneous finding	Table top not adhered to legs (safety item).	111	administration	Yes
FXPVMS202300245B	Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)	A microwave and refrigerator were observed. If not serving an educational purpose, these items are recommended to be removed to improve energy conservation.	129	administration	Yes
FXPVMS202300245C	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	Return vent dirty and requires cleaning (Custodial) and blocked by portable air purifier. It is recommended that the return vent have a minimum of three feet of clearance (Administration).	Cafeteria	custodial	Yes
FXPVMS202300245D	Stained/damaged tiles	Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile.	Student Services - Conference Room	custodial	Yes
FXPVMS202300245E	Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)	Microwave and coffee machine observed. If not serving an educational purpose, these items are recommended to be removed to improve energy conservation.	Student Support	administration	Yes
FXPVMS202300245F	Wall-mounted unit requires cleaning/general preventative maintenance	Wall mounted HVAC units are off. Building Maintenance is to assess.	Gym Locker Room Offices and Fitness Room	building	Yes
FXPVMS2023002460	Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)	Various appliances were observed. If not serving an educational purpose, these items are recommended to be removed to improve energy conservation.	Orchestra ("chorus") Planning	administration	Yes
FXPVMS2023002461	Stained/damaged tiles	Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile.	Art 2		No
FXPVMS2023002462	Stained/damaged tiles	Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile.	Art Storage	custodial	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXPVMS2023002484	Miscellaneous finding	Mandatory lead signage above the exterior hose bib has been removed/vandalized and needs to be replaced.	Exterior	building	Yes