

# Findings for walkthrough Hammond High School: January 24th, 2019

## (WXHAHS2019000113)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXHAHS201900077F	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	Supply diffusers rusty, in general throughout. Place work order for Building Services to re-paint or replace.	General	building	Yes
FXHAHS2019000781	Tight seal on ceiling tiles		604	custodial	Yes
FXHAHS2019000782	Elevated moisture per moisture meter		604	environmental	Yes
FXHAHS2019000783	Tight seal on ceiling tiles		Kitchen Office	custodial	Yes
FXHAHS2019000784	Plumbing fixture leaking/draining slowly		609	building	Yes
FXHAHS2019000785	Elevated moisture per moisture meter		610	environmental	Yes
FXHAHS2019000786	Tight seal on ceiling tiles		611	custodial	Yes
FXHAHS2019000787	Air freshener/essential oils		Custodial Locker Room	administration	Yes
FXHAHS2019000788	Miscellaneous finding	Missing light panel	Science prep		No
FXHAHS2019000789	Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)		Band Office	administration	Yes
FXHAHS201900078A	General Cleanliness/Dust		Band Office	administration	Yes
FXHAHS201900078B	Tight seal on ceiling tiles	Hole in tile	Band Office	custodial	Yes
FXHAHS201900078D	Chemicals are capped	Storage Height (fire code)	Band Storage	administration	Yes
FXHAHS201900078F	Tight seal on ceiling tiles		510	custodial	Yes
FXHAHS2019000790	Tight seal on ceiling tiles	Stained tile	213	custodial	Yes
FXHAHS2019000791	Uncomfortable temperature	Usally hot	Media	building	Yes
FXHAHS2019000792	Elevated moisture per moisture meter		522	environmental	Yes
FXHAHS2019000793	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	Both electrical rooms across from 103	Electrical Room across from103	administration	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXHAHS2019000794	Elevated moisture per moisture meter	Stagecraft - Suspect mold growth on insulation. Office of environment will submit a work order.	521	environmental	Yes
FXHAHS2019000796	Tight seal on ceiling tiles		304	custodial	Yes
FXHAHS2019000797	Tight seal on ceiling tiles		304 closet	custodial	Yes
FXHAHS2019000798	Miscellaneous finding		auditorium	environmental	Yes
FXHAHS201900079A	Elevated moisture per moisture meter	Stagecraft - material in front of door blocking. Wood on floor with nails sticking up - Extremely unsafe.	518	environmental	Yes
FXHAHS201900079B	Miscellaneous finding		auditorium		No
FXHAHS201900079C	Tight seal on ceiling tiles		303 storage	custodial	Yes
FXHAHS201900079E	Tight seal on ceiling tiles		303 office	custodial	Yes
FXHAHS201900079F	Windows/Doors open		505	building	Yes
FXHAHS20190007A0	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		302	administration	Yes
FXHAHS20190007A1	Tight seal on ceiling tiles		302	custodial	Yes
FXHAHS20190007A2	General Cleanliness/Dust		302	custodial	Yes
FXHAHS20190007A3	Tight seal on ceiling tiles		516	custodial	Yes
FXHAHS20190007A4	Tight seal on ceiling tiles		501	custodial	Yes
FXHAHS20190007A5	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		501	administration	Yes
FXHAHS20190007A6	Elevated moisture per moisture meter		226	environmental	Yes
FXHAHS20190007A7	Tight seal on ceiling tiles		228	custodial	Yes
FXHAHS20190007A8	Tight seal on ceiling tiles		Boys Team Room	custodial	Yes
FXHAHS20190007A9	Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)	Large amount of furniture in storage closet, should be removed to prevent summer mold growth issues. If the items are not being used, discard.	Boys Locker	administration	Yes
FXHAHS20190007AB	Tight seal on ceiling tiles	Boys Locker Room office	Boys Locker	custodial	Yes
FXHAHS20190007AD	Elevated moisture per moisture meter		230	environmental	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXHAHS20190007AE	Plumbing fixture leaking/draining slowly		230	building	Yes
FXHAHS20190007AF	Elevated moisture per moisture meter		Art closet	environmental	Yes
FXHAHS20190007B0	Tight seal on ceiling tiles	Missing tile, water damaged tiles	217	custodial	Yes
FXHAHS20190007B1	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		607	administration	Yes
FXHAHS20190007B2	Tight seal on ceiling tiles	Missing tile	Training Room Boys Locker Room	custodial	Yes
FXHAHS20190007B6	Plumbing fixture leaking/draining slowly		Guidance sink	custodial	Yes