

IEQ Concern Form School Facilities IEQ Coordinator

<u>Instructions</u> : Complete this form if you believe that you have a concern about the indoor environmental quality of a HCPSS building or facility. The form is to be submitted to the HCPSS IEQ Coordinator. You will be contacted within 5 working days regarding your concern.
Name of person completing the form: Laura Duggan Date of this request: 12-8-16 Student X Staff Parent Visitor Contact information: Phone: 410-880-5890 Email: laura_duggan@hcpss.org
School Building/Facility: Hammond Elementary Location (specific room or area) Storage Closet Room 95
Briefly describe the concern or problem. Have you attached a photo? no Date of photo:
During our semi-annual walkthrough, a suspicious growth was located on the ceiling of the storage closet off Room 95. HCPSS is aware and responding. When did you notice the problem: 12-8-16
Action taken by HCPSS:
Discoloration was found along the wall and ceiling - the material running down the wall was not mold, but product from roof replacement or construction. The speckled pattern on the upper steel beam was suspect mold. The staining was cleaned and disinfected using custodial product Q128 (EPA registered). The cause appears to be thermal surface differential (metal conducting/influenced by outdoor air temperature/draft and the indoor temperature forming condensate). It is undetermined if past (during construction) or present. A work team will continue to evaluate but no current growth identified.
Name / Signature of the HCPSS person responding:The Office of the Environment