

Findings for walkthrough Thomas Viaduct Middle School: April 10th, 2024 (WXTVMS2024000506)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXTVMS2024002811	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	Return dusty and requires cleaning.	210	custodial	Yes
FXTVMS2024002812	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The supply diffusers are visibly dirty and require dusting/cleaning.	212	custodial	Yes
FXTVMS2024002813	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The supply diffusers are visibly dirty and require dusting/cleaning.	223	custodial	Yes
FXTVMS2024002814	Extinguisher not singed off on within the last month		2nd Floor Sci Prep	custodial	Yes
FXTVMS2024002816	Extinguisher not singed off on within the last month		Outside 245	custodial	Yes
FXTVMS2024002817	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The supply diffusers are visibly dirty and require dusting/cleaning.	A78	custodial	Yes
FXTVMS2024002819	Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)	Various appliances such as refrigerators and toasters were observed. If not serving an educational purpose, these items are recommended to be removed to improve energy conservation.	A68	administration	Yes
FXTVMS202400281A	Air freshener/essential oils	Remind staff air fresheners, plug-ins, scent oil sticks, etc. are not permitted because they can mask an odor of concern and/or be an irritant to other individuals.	A68	administration	Yes
FXTVMS202400281B	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The supply diffusers are visibly dirty and require dusting/cleaning.	A56	custodial	Yes
FXTVMS202400281C	Miscellaneous finding	Food product readily accessible to pests. Place food item in a durable and sealable container and place in an elevated cabinet and/or drawer.	1st Floor Sci Prep	administration	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXTVMS202400281E	Obstruction(s) to airflow	Return blocked by desk. It is recommended that the return vent have a minimum of three feet of clearance to facilitate air movement through the space.	A40	administration	Yes
FXTVMS202400281F	Wall-mounted unit requires cleaning/general preventative maintenance		MDF Room	building	Yes
FXTVMS2024002821	Extinguisher not singed off on within the last month		A37	custodial	Yes
FXTVMS2024002824	Wall-mounted unit requires cleaning/general preventative maintenance		Gym Office	building	Yes
FXTVMS2024002825	Miscellaneous finding	The showers are being used for storage. The storage items should be re-configured to allow the custodian complete access to the multiple floor drains around the perimeter of the shower without having to move items. If the floor drains are not filled with water occasionally (monthly to quarterly), sewer gas odors can backflow into the locker room.	Locker Room	administration	Yes
FXTVMS2024002826	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The supply diffusers are visibly dirty and require dusting/cleaning.	B33	custodial	Yes
FXTVMS2024002829	Extinguisher not singed off on within the last month		Kitchen	custodial	Yes
FXTVMS202400282A	Extinguisher not singed off on within the last month		B14	custodial	Yes
FXTVMS202400282B	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The supply diffusers are visibly dirty and require dusting/cleaning.	B15	custodial	Yes
FXTVMS202400282C	Miscellaneous finding	Stat lock box not attached to wall (anchors loose).	Portable 270	building	Yes
FXTVMS202400282D	Miscellaneous finding	Stat lock box not attached to wall (anchors loose).	Portable 271	building	Yes
FXTVMS202400282E	Extinguisher not singed off on within the last month		Portable 270	custodial	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXTVMS202400282F	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The return is visibly dirty and requires dusting/cleaning.	Portable 271	custodial	Yes
FXTVMS202400284B	Obstruction(s) to airflow	Return air partially blocked. It is recommended that the return have a minimum of 3 feet of clearance.	210	administration	Yes