

Findings for walkthrough Patuxent Valley Middle School: November 14th, 2019 (WXPVMS2019000250)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXPVMS20190014A1	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		Health room	custodial	Yes
FXPVMS20190014A2	Tight seal on ceiling tiles		122	custodial	Yes
FXPVMS20190014A4	Tight seal on ceiling tiles		FACS	custodial	Yes
FXPVMS20190014A5	General Cleanliness/Dust	Music Office - dead bug in lights	209	custodial	Yes
FXPVMS20190014A8	Tight seal on ceiling tiles		Outside of music	custodial	Yes
FXPVMS20190014A9	Tight seal on ceiling tiles		ALS	custodial	Yes
FXPVMS20190014AA	Electrical wiring exposed or disconnected wires		128	building	Yes
FXPVMS20190014AB	Tight seal on ceiling tiles		128	custodial	Yes
FXPVMS20190014AC	Chemicals are capped	Housekeeping	Gym Storage	administration	Yes
FXPVMS20190014AE	Tight seal on ceiling tiles		Gym Vestibule	custodial	Yes
FXPVMS20190014AF	Tight seal on ceiling tiles		132	custodial	Yes
FXPVMS20190014B0	Miscellaneous finding	Zip tie on sprinkler main - Assign WO to Plumbing	Boiler Room	building	Yes
FXPVMS20190014B2	Tight seal on ceiling tiles		150	custodial	Yes
FXPVMS20190014B3	Miscellaneous finding	Inspect and sign off on fire extinguisher	Boys Locker Room	custodial	Yes
FXPVMS20190014B5	Electrical equipment near sinks or source of water		Bathroom next to Custodial Office	custodial	Yes
FXPVMS20190014B6	Tight seal on ceiling tiles		Outside 135	custodial	Yes
FXPVMS20190014B7	Tight seal on ceiling tiles		Girls bathroom	custodial	Yes
FXPVMS20190014B8	Tight seal on ceiling tiles		Boys bathroom	custodial	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXPVMS20190014B9	Tight seal on ceiling tiles		Stage Ramp Storage	custodial	Yes
FXPVMS20190014BA	Electrical outlets not secured, cover missing, frayed wires on equipment		Bookroom	building	Yes
FXPVMS20190014BB	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		Kitchen office	custodial	Yes
FXPVMS20190014BC	Tight seal on ceiling tiles		Data clerk	custodial	Yes
FXPVMS20190014BD	Tight seal on ceiling tiles		Data clerk	custodial	Yes
FXPVMS20190014BE	Tight seal on ceiling tiles		130	custodial	Yes
FXPVMS20190014BF	Chemicals are capped	Inspect and Sign Off on Fire Extinguisher	Tractor Storage	custodial	Yes
FXPVMS20190014C0	Holes/Penetrations in Wall	Missing brick near roof line.	Exterior Wall Outside of Locker Rooms	building	Yes