

Findings for walkthrough Applications and Research Laboratory: November 12th, 2018 (WXXARL2018000076)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXARL201800012B	Tight seal on ceiling tiles		Conference Room	custodial	Yes
FXXARL201800012C	Miscellaneous finding	back left of room pipe up in the ceiling is flaking paint	a20	building	No
FXXARL201800012E	Miscellaneous finding	Flaking paint up in top back corner at ceiling level. Prior leak in the same back corner water stains on the floor. Not sure if leak resolved.	a14	building	No
FXXARL2018000131	Elevated moisture per moisture meter		a13	environmental	Yes
FXXARL2018000134	Miscellaneous finding	Flaking paint on pipe along wall	a13	building	No
FXXARL2018000136	Tight seal on ceiling tiles		c28	custodial	Yes
FXXARL2018000137	Tight seal on ceiling tiles		C29	custodial	Yes
FXXARL2018000138	Miscellaneous finding	Individual indicating eyes are itchy - she should submit an IEQ concern.	C29	environmental	Yes
FXXARL201800013A	Relative humidity above 70%	On supply diffuser	C37a	environmental	Yes
FXXARL201800013C	Tight seal on ceiling tiles	Several tiles in room and in adjoining closet.	c42-2	custodial	Yes
FXXARL201800013E	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		Women's bath next to c42	administration	Yes
FXXARL201800013F	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		Women's bath next to c42	administration	Yes
FXXARL2018000140	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		Men's bath near c42	administration	Yes
FXXARL2018000141	Tight seal on ceiling tiles	Front of room	c55	custodial	Yes
FXXARL2018000144	Tight seal on ceiling tiles	Stain very dark, replace ceiling tile	B37	custodial	Yes
FXXARL2018000146	Tight seal on ceiling tiles	Outside b64 near window	b65_hall	custodial	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXARL2018000148	Tight seal on ceiling tiles	Near pipe	Chen Storage within b62	custodial	Yes
FXXARL201800014A	Artificial plants/trees	Live plants should have a secondary containment.	b66	administration	Yes
FXXARL201800014C	Tight seal on ceiling tiles		Men's bath d wing	custodial	Yes
FXXARL201800014D	Tight seal on ceiling tiles	In closet and in front of closet.	Closet in front of D28	custodial	Yes
FXXARL201800014F	Tight seal on ceiling tiles		d22	custodial	Yes
FXXARL2018000151	Elevated moisture per moisture meter	Back closet, previously repaired	A14	environmental	Yes
FXXARL2018000152	Uncomfortable temperature	too hot or too cold	A2	building	No
FXXARL2018000153	Tight seal on ceiling tiles	Wide open ceiling tile with cords hanging down out of it Water stained tiles back corner of room near B46 and corner of back window Dark stain, tile needs to be removed	B46	custodial	Yes
FXXARL2018000154	General Cleanliness/Dust	Dead insects in light fixture when first walk in room	B48	custodial	Yes
FXXARL2018000155	Miscellaneous finding	Peeling paint around air supply/return	B48		No
FXXARL2018000156	General Cleanliness/Dust	Dirty supply/return register in closet adjacent to women's bathroom	Custodian Office and Bathrooms	custodial	Yes
FXXARL2018000157	Miscellaneous finding	Peeling paint and rusty looking pipes under sink in Mens' bathroom in Custodial office	Custodian Office and Bathrooms	building	No
FXXARL2018000158	General Cleanliness/Dust	Closet has debris on the floor	D6	custodial	Yes
FXXARL2018000159	Tight seal on ceiling tiles		D6	custodial	Yes
FXXARL201800015A	Tight seal on ceiling tiles	stained and missing tiles	D20 Print Shop	custodial	Yes
FXXARL201800015B	Uncomfortable temperature	Continuous cold air blows out from ceiling supply, very cold	D21	building	No