

Findings for walkthrough Applications and Research Laboratory: November 12th, 2018 (WXXARL2018000076)

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|--|--------------------------|----------------|--------|
| FXXARL201800012B | Tight seal on ceiling tiles | | Conference Room | custodial | Yes |
| FXXARL201800012C | Miscellaneous finding | back left of room pipe up in the ceiling is flaking paint | a20 | building | No |
| FXXARL201800012E | Miscellaneous finding | Flaking paint up in top back corner at ceiling level. Prior leak in the same back corner water stains on the floor. Not sure if leak resolved. | a14 | building | No |
| FXXARL2018000131 | Elevated moisture per moisture meter | | a13 | environmental | Yes |
| FXXARL2018000134 | Miscellaneous finding | Flaking paint on pipe along wall | a13 | building | No |
| FXXARL2018000136 | Tight seal on ceiling tiles | | c28 | custodial | Yes |
| FXXARL2018000137 | Tight seal on ceiling tiles | | C29 | custodial | Yes |
| FXXARL2018000138 | Miscellaneous finding | Individual indicating eyes are itchy - she should submit an IEQ concern. | C29 | environmental | Yes |
| FXXARL201800013A | Relative humidity above 70% | On supply diffuser | C37a | environmental | Yes |
| FXXARL201800013C | Tight seal on ceiling tiles | Several tiles in room and in adjoining closet. | c42-2 | custodial | Yes |
| FXXARL201800013E | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | Women's bath next to c42 | administration | Yes |
| FXXARL201800013F | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | Women's bath next to c42 | administration | Yes |
| FXXARL2018000140 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | Men's bath near c42 | administration | Yes |
| FXXARL2018000141 | Tight seal on ceiling tiles | Front of room | c55 | custodial | Yes |
| FXXARL2018000144 | Tight seal on ceiling tiles | Stain very dark, replace ceiling tile | B37 | custodial | Yes |
| FXXARL2018000146 | Tight seal on ceiling tiles | Outside b64 near window | b65_hall | custodial | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--------------------------------------|--|--------------------------------|----------------|--------|
| FXXARL2018000148 | Tight seal on ceiling tiles | Near pipe | Chen Storage within b62 | custodial | Yes |
| FXXARL201800014A | Artificial plants/trees | Live plants should have a secondary containment. | b66 | administration | Yes |
| FXXARL201800014C | Tight seal on ceiling tiles | | Men's bath d wing | custodial | Yes |
| FXXARL201800014D | Tight seal on ceiling tiles | In closet and in front of closet. | Closet in front of D28 | custodial | Yes |
| FXXARL201800014F | Tight seal on ceiling tiles | | d22 | custodial | Yes |
| FXXARL2018000151 | Elevated moisture per moisture meter | Back closet, previously repaired | A14 | environmental | Yes |
| FXXARL2018000152 | Uncomfortable temperature | too hot or too cold | A2 | building | No |
| FXXARL2018000153 | Tight seal on ceiling tiles | Wide open ceiling tile with cords hanging down out of it Water stained tiles back corner of room near B46 and corner of back window Dark stain, tile needs to be removed | B46 | custodial | Yes |
| FXXARL2018000154 | General Cleanliness/Dust | Dead insects in light fixture when first walk in room | B48 | custodial | Yes |
| FXXARL2018000155 | Miscellaneous finding | Peeling paint around air supply/return | B48 | | No |
| FXXARL2018000156 | General Cleanliness/Dust | Dirty supply/return register in closet adjacent to women's bathroom | Custodian Office and Bathrooms | custodial | Yes |
| FXXARL2018000157 | Miscellaneous finding | Peeling paint and rusty looking pipes under sink in Mens' bathroom in Custodial office | Custodian Office and Bathrooms | building | No |
| FXXARL2018000158 | General Cleanliness/Dust | Closet has debris on the floor | D6 | custodial | Yes |
| FXXARL2018000159 | Tight seal on ceiling tiles | | D6 | custodial | Yes |
| FXXARL201800015A | Tight seal on ceiling tiles | stained and missing tiles | D20 Print Shop | custodial | Yes |
| FXXARL201800015B | Uncomfortable temperature | Continuous cold air blows out from ceiling supply, very cold | D21 | building | No |