

Findings for walkthrough Mount View Middle School: November 14th, 2018 (WXMVMS2018000083)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXMVMS201800019B	Electrical cords unsecured, extend across walkways, cord protectors not installed		11	administration	Yes
FXMVMS201800019C	Tight seal on ceiling tiles		Psyc office	custodial	Yes
FXMVMS201800019D	Plumbing fixture leaking/draining slowly	Hot water faucet at demonstration sink leaks	Facs	building	No
FXMVMS201800019E	Plumbing fixture leaking/draining slowly		Facs	building	No
FXMVMS201800019F	Tight seal on ceiling tiles		Outside of staff work room	custodial	Yes
FXMVMS20180001A0	Uncomfortable temperature		17	building	No
FXMVMS20180001A2	Uncomfortable temperature		17a	building	No
FXMVMS20180001A3	Uncomfortable temperature		20	building	No
FXMVMS20180001A4	Plumbing fixture leaking/draining slowly		22	building	No
FXMVMS20180001A5	Electrical cords unsecured, extend across walkways, cord protectors not installed		23	administration	Yes
FXMVMS20180001A6	Electrical cords unsecured, extend across walkways, cord protectors not installed		24	administration	Yes
FXMVMS20180001A7	Electrical cords unsecured, extend across walkways, cord protectors not installed		Rm 2	administration	Yes
FXMVMS20180001A8	Electrical cords unsecured, extend across walkways, cord protectors not installed		3	administration	Yes
FXMVMS20180001A9	Tight seal on ceiling tiles		Sped office	custodial	Yes
FXMVMS20180001AA	Windows/Doors open	Windows left open	Dance	administration	Yes
FXMVMS20180001AC	Plumbing fixture leaking/draining slowly	Teacher noted an occassional dripping sound. Facilities should check for potential leaks.	Choral Room	building	No

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXMVMS20180001AE	Tight seal on ceiling tiles	Across from water fountain.	Hallway Tech Ed	custodial	Yes
FXMVMS20180001B0	Tight seal on ceiling tiles		Custodial storage near tech ed	custodial	Yes
FXMVMS20180001B1	Plumbing fixture leaking/draining slowly	Leaky pipe within freezer	Freezer	custodial	Yes
FXMVMS20180001B3	Plumbing fixture leaking/draining slowly	Dishwasher leaking	Kitchen - dishwashing	building	No
FXMVMS20180001B5	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	Dirty supply diffusers	Tech Ed Project Storage	administration	Yes
FXMVMS20180001B8	Electrical cords unsecured, extend across walkways, cord protectors not installed		6	administration	Yes
FXMVMS20180001BF	Electrical cords unsecured, extend across walkways, cord protectors not installed	Electrical cord covers missing	Rm6, Rm8, Rm9a		No
FXMVMS20180001C1	Tight seal on ceiling tiles	Pipes need insulation	Hall outside of work room		No