

Findings for walkthrough Long Reach High School: November 16th, 2018 (WXRHS201800008A)

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|--|------------------|----------------|--------|
| FXLRHS20180001C0 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | Toaster oven | b103-2 | administration | Yes |
| FXLRHS20180001C3 | Chemicals are capped | Closet may need to be organized - possible egress issue if there is an emergency | Tech Ed storage | administration | Yes |
| FXLRHS20180001C5 | Electrical cords unsecured, extend across walkways, cord protectors not installed | | 328 | custodial | Yes |
| FXLRHS20180001C6 | Electrical cords unsecured, extend across walkways, cord protectors not installed | | 326 | custodial | Yes |
| FXLRHS20180001C7 | Odors | | 324 | environmental | Yes |
| FXLRHS20180001C8 | Artificial plants/trees | | 322 | administration | Yes |
| FXLRHS20180001C9 | Excessive stuffed animals | | 322 | administration | Yes |
| FXLRHS20180001CA | Excessive stuffed animals | | 320 Admin Office | administration | Yes |
| FXLRHS20180001CB | Artificial plants/trees | | 320 Admin Office | administration | Yes |
| FXLRHS20180001CC | Tight seal on ceiling tiles | | b128 | custodial | Yes |
| FXLRHS20180001CD | Visible mold (leak) | Possible in the corner | Stair well | environmental | Yes |
| FXLRHS20180001CE | Uncomfortable temperature | | gym | building | No |
| FXLRHS20180001D0 | Tight seal on ceiling tiles | | a123 | custodial | Yes |
| FXLRHS20180001D1 | Tight seal on ceiling tiles | | a123 | custodial | Yes |
| FXLRHS20180001D2 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | b107a | administration | Yes |
| FXLRHS20180001D3 | Electrical cords unsecured, extend across walkways, cord protectors not installed | | 318 | custodial | Yes |
| FXLRHS20180001D4 | Miscellaneous finding | Pipe covers missing | Girls bathroom | building | No |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|--|--------------------------|----------------|--------|
| FXLRHS20180001D6 | Tight seal on ceiling tiles | | b122 | custodial | Yes |
| FXLRHS20180001D7 | Tight seal on ceiling tiles | | 314_hall | custodial | Yes |
| FXLRHS20180001D8 | Tight seal on ceiling tiles | | auditorium_entrance_hall | custodial | Yes |
| FXLRHS20180001D9 | Tight seal on ceiling tiles | | b123 | custodial | Yes |
| FXLRHS20180001DA | Artificial plants/trees | | 316 | administration | Yes |
| FXLRHS20180001DB | Relative humidity above 70% | | 312 | environmental | Yes |
| FXLRHS20180001DC | Tight seal on ceiling tiles | | 311 | custodial | Yes |
| FXLRHS20180001DD | Tight seal on ceiling tiles | | auditorium_side_hall | custodial | Yes |
| FXLRHS20180001DE | Electrical outlets not secured, cover missing, frayed wires on equipment | | 307 | building | Yes |
| FXLRHS20180001DF | Tight seal on ceiling tiles | | 3rd floor C stairwell | custodial | Yes |
| FXLRHS20180001E0 | Electrical cords unsecured, extend across walkways, cord protectors not installed | | 306 | custodial | Yes |
| FXLRHS20180001E1 | Artificial plants/trees | | 306 | administration | Yes |
| FXLRHS20180001E2 | Odors | Nail polish spill smell | 306 | environmental | Yes |
| FXLRHS20180001E4 | Miscellaneous finding | Taxidermy hanging above door | 306 | administration | Yes |
| FXLRHS20180001E6 | Tight seal on ceiling tiles | | 304 | custodial | Yes |
| FXLRHS20180001E7 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | 304 | administration | Yes |
| FXLRHS20180001E8 | Miscellaneous finding | Missing camera cover on ceiling | 302_hall | building | No |
| FXLRHS20180001E9 | Electrical cords unsecured, extend across walkways, cord protectors not installed | | 302 | custodial | Yes |
| FXLRHS20180001EA | Tight seal on ceiling tiles | 3 tiles are stained in the class. 2 missing at exit door. Wet tile at back door. Large trash bin blocking exit to catch water? | 356 | custodial | Yes |
| FXLRHS20180001EB | Tight seal on ceiling tiles | Two ceiling tiles | 250 | custodial | Yes |
| FXLRHS20180001EE | Miscellaneous finding | Missing covers on ceiling cameras and sprinkler heads dirty on side closest to library | Hallway | building | No |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|---|--|-----------------------|----------------|--------|
| FXLRHS20180001F0 | Tight seal on ceiling tiles | | 354 | custodial | Yes |
| FXLRHS20180001F1 | Electrical cords unsecured, extend across walkways, cord protectors not installed | | 354 | custodial | Yes |
| FXLRHS20180001F2 | Electrical cords unsecured, extend across walkways, cord protectors not installed | | 348 | custodial | Yes |
| FXLRHS20180001F3 | Odors | Staff report carpet smells | 348 | environmental | Yes |
| FXLRHS20180001F5 | Tight seal on ceiling tiles | Water stain near tv and in front of screen | 350 | custodial | Yes |
| FXLRHS20180001F6 | Tight seal on ceiling tiles | | 353 Prep Room | custodial | Yes |
| FXLRHS20180001F8 | Electrical cords unsecured, extend across walkways, cord protectors not installed | | 352 | custodial | Yes |
| FXLRHS20180001F9 | Electrical outlets not secured, cover missing, frayed wires on equipment | No emergency electrical shut-off, science room | 356 | building | Yes |
| FXLRHS20180001FA | Miscellaneous finding | No drain for eye wash and shower. Consider putting pig skins in room to absorb water if needed | 352 | building | No |
| FXLRHS20180001FE | Miscellaneous finding | No water pipe covers under sinks | Girl bathroom | building | No |
| FXLRHS2018000200 | Tight seal on ceiling tiles | | 348 | custodial | Yes |
| FXLRHS2018000201 | Electrical cords unsecured, extend across walkways, cord protectors not installed | | 344 | custodial | Yes |
| FXLRHS2018000202 | Tight seal on ceiling tiles | | 343 | custodial | Yes |
| FXLRHS2018000203 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cords are tangled and overlapping power strip | 343 | custodial | Yes |
| FXLRHS2018000205 | Tight seal on ceiling tiles | Water stain | 340 | custodial | Yes |
| FXLRHS2018000207 | Miscellaneous finding | Tile and cardboard near warm electrical equipment. | 339 electrical closet | custodial | Yes |
| FXLRHS2018000208 | Miscellaneous finding | Damaged counter top edge | 340 | building | No |
| FXLRHS201800020B | Miscellaneous finding | Clearance issue n storage shelves, too close to ceiling | 337 | administration | Yes |
| FXLRHS201800020D | Relative humidity above 70% | Evidence of water damage on the window sill | 334 | environmental | Yes |
| FXLRHS201800020F | Excessive stuffed animals | | 334 | administration | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------------|---|-----------------------------|-----------------|--------------------|---------------|
| FXLRHS2018000210 | Electrical cords unsecured, extend across walkways, cord protectors not installed | | 332 | custodial | Yes |
| FXLRHS2018000211 | Odors | When HVAC runs, musty smell | 335 | environmental | Yes |
| FXLRHS2018000213 | Signs of insects or evidence of pest | | 335 | building | Yes |