

Findings for walkthrough Centennial Lane Elementary School: October 12th, 2022 (WXCLES20220003EF)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXCLES2022001FD0	Stained/damaged tiles	Water stained ceiling tiles. Custodial is to place a work order for Building Maintenance to address if one is not already in progress.	110, 114, 124, and boy's restroom near room 124	custodial	Yes
FXCLES2022001FD1	Tight seal on ceiling tiles	A couple of ceiling tiles are not tightly fitting within grid.	Storage in auxiliary gym	custodial	Yes
FXCLES2022001FD2	Visible mold (leak)	Small areas of the metal roofing system has mold spotting and on underside of a pipe. See IEQ Concern #CXCLES2022000253 for additional details (note, the concern report will not be available until remedial work is complete).	Auxiliary Gym	building	Yes
FXCLES2022001FD3	Short Circuiting between supply and return	There are 3 ducted returns located in the ceiling. There are 2 air supply diffusers in close proximity.	Room 129	building	Yes
FXCLES2022001FD4	Miscellaneous finding	The sensory table (2 compartments usually contains sand, rice, etc.) contained a small amount of real foliage which can be a potential allergen (mold on foliage) to some individuals when handled/disturbed.	Room 141	administration	Yes
FXCLES2022001FD5	Penetrations not sealed	The caulking is deteriorating around the exterior electrical conduit penetrating the exterior siding.	Portable 88	building	Yes
FXCLES2022001FD6	Electrical outlets not secured, cover missing, frayed wires on equipment	Outlet cover plate is missing.	Portable 149	building	Yes
FXCLES2022001FD7	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	A leaf and pine needles noted within some air supply diffusers.	Portable 149	building	Yes
FXCLES2022001FD8	Miscellaneous finding	Paint is peeling around one window.	Auxiliary Gym	building	Yes