

IEQ Concern Form School Facilities IEQ Coordinator

<u>Instructions</u> : Complete this form if you believe that you have a environmental quality of a HCPSS building or facility. The for HCPSS IEQ Coordinator. You will be contacted within 5 work	m is to be submitted to the
Name of person completing the form: Carol Flahm Student \( \subseteq \) StaffParentVisitor  Contact information: Phone: \( \frac{410}{313} \) \( \frac{5057}{5057} \) Email: \( \frac{Caro}{0} \)  School Building/Facility: \( \frac{bellows}{0} \) \( \frac{5007}{5057} \) Location (specified)  Briefly describe the concern or problem. Have you attached a p	Date of this request: 12/7/2016  1-hahn @ hapss.org  ific room or area) Storage Closet  arms from otherade
Approximately to linear feet of stained drywall at Stain was to 8 inches above the baseboard.  When did you notice the problem: Dec. 7, 2014	the back of closet. The
Action taken by HCPSS:  Jeff Klank immediately contacted principle We also called building Services. The cust wall and the items in closet inspected. Le the drywall near the bottom.	a) and day chief custodian. Todian aleaned the Building services removed
Name / Signature of the HCPSS person responding: <u>Caralle</u>	Hahr_