

Findings for walkthrough Stevens Forest Elementary School: August 15th, 2023 (WXSFE2023000490)

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|-----------------------|--|---------------------------|-------------|--------|
| FXSFES2023002592 | Miscellaneous finding | Fire extinguisher behind monthly inspection. Last inspected in May 2023. Perform monthly. | Hallway near front office | custodial | Yes |
| FXSFES2023002597 | Miscellaneous finding | Fire extinguisher behind monthly inspection. Last inspected in October 2022. Perform monthly. | Portable # 105 | custodial | Yes |
| FXSFES2023002598 | Miscellaneous finding | Heating and ventilation unit running while it's not occupied during summer break. Appears to be bringing in hot and humid air from outside and making the gym even more uncomfortable. Building Maintenance to review the HVAC controls and schedule settings to ensure units are not running during summer while gym is not occupied. | Gym | building | Yes |
| FXSFES2023002599 | Miscellaneous finding | Space temperature 69.3 deg. Majority of the areas in the building are being overcooled into the low 70 deg. or even high 60 deg. The temperature is several degrees below the standard of HCPSS Guidelines for Energy Conservation setting of 76 deg. for cooling mode. Building Maintenance to review the HVAC controls and temperature settings to maintain proper temperature and improve energy conservation. | Cafeteria | building | Yes |
| FXSFES202300259A | Miscellaneous finding | Space temperature 69.9 deg. Majority of the areas in the building are being overcooled into the low 70 deg. or even high 60 deg. The temperature are several degrees below the standard of HCPSS Guidelines for Energy Conservation setting of 76 deg. for cooling mode. Building Maintenance to review the HVAC controls and temperature settings to maintain proper temperature and improve energy conservation. | Health Suite | building | Yes |
| FXSFES20230025C1 | Miscellaneous finding | Thermostat cooling set point set at 74 degrees F. Per the HCPSS Summer Operation Schedule, the set point is to be 82 degrees F. | Portable #109 | building | Yes |
| FXSFES20230025C2 | Miscellaneous finding | Thermostat cooling set point set at 74 degrees F. Per the HCPSS Summer Operation Schedule, the set point is to be 82 degrees F. | Portable # 103 | building | Yes |
| FXSFES20230025C3 | Miscellaneous finding | Thermostat cooling set point set at 74 degrees F. Per the HCPSS Summer Operation Schedule, the set point is to be 82 degrees F. | Portable # 105 | building | Yes |
| FXSFES20230025C4 | Miscellaneous finding | Thermostat cooling set point set at 74 degrees F. Per the HCPSS Summer Operation Schedule, the set point is to be 82 degrees F. | Portable # 170 | building | Yes |
| FXSFES20230025C5 | Miscellaneous finding | Thermostat display screen blank. | Portable # 31 | building | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|-------------------------------|--|---------------|----------------|--------|
| FXSFES20230025C6 | 18" Of Clearance from Ceiling | Miscellaneous items stored less than 18 inches from the ceiling. Remove/reconfigure to allow for 18" of clearance. | Classroom 046 | administration | Yes |