

Findings for walkthrough Wilde Lake Middle School: May 29th, 2024 (WXWLMS2024000519)

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|---|---|---------------------|----------------|--------|
| FXWLMS2024002901 | Miscellaneous finding | Missing lead signage. | A28, A32 | building | No |
| FXWLMS2024002902 | Obstruction(s) to airflow | The return vent was blocked by mats. It is recommended that the return vent have a minimum of three feet of clearance to facilitate air movement through the space. | A34 | administration | Yes |
| FXWLMS2024002903 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | An electric kettle was observed. If not serving an educational purpose, these items are recommended to be removed to improve energy conservation. | A77 | administration | Yes |
| FXWLMS2024002904 | Miscellaneous finding | Missing lead signage. | A44 | building | No |
| FXWLMS2024002905 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | An electric kettle was observed. If not serving an educational purpose, these items are recommended to be removed to improve energy conservation. | A44 | administration | Yes |
| FXWLMS2024002906 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | A coffee maker was observed. If not serving an educational purpose, these items are recommended to be removed to improve energy conservation. | 259 | administration | Yes |
| FXWLMS2024002907 | Miscellaneous finding | Missing lead signage. | 243 | building | No |
| FXWLMS2024002908 | Miscellaneous finding | Missing lead signage. | 232, 230, 226 | building | No |
| FXWLMS2024002909 | Miscellaneous finding | Missing lead signage. | Exterior Door 33 | building | No |