

Findings for walkthrough Mount View Middle School: January 8th, 2025 (WXMVMS2025000595)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXMVMS2025002C9F	Miscellaneous finding	Lockbox around the thermostat was removed.	Portable 63	building	No
FXMVMS2025002CA0	Artificial plants/trees	Artificial plants easily collect dust (potential allergen) and are difficult to clean. This item is to be removed.	Portable 63	administration	Yes
FXMVMS2025002CA1	Non-issued disinfectants/aerosol sprays	A non-issued disinfectant spray was observed within classroom. Such products are not permitted since they can be an airborne irritant when used. Disinfectant wipes and/or the approved cleaning solution from Custodial are permitted.	Portable 63	administration	Yes
FXMVMS2025002CA2	Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)	A miniature refrigerator was observed. If not serving an educational purpose, these items are recommended to be removed to improve energy conservation.	Portable 64	administration	Yes
FXMVMS2025002CA3	Air freshener/essential oils	Remind staff air fresheners, plug-ins, scent oil sticks, etc. are not permitted because they can mask an odor of concern and/or be an irritant to other individuals.	Portable 64	administration	Yes
FXMVMS2025002CA4	Excessive stuffed animals	Stuffed animals and decorative flags were present and appear non-school issued. These items may house allergens if not properly maintained. Remove unnecessary materials or ensure teaching staff has and is following a cleaning schedule (launder or vacuum) since not the responsibility of custodial staff to clean non-school items.	Portable 273	administration	Yes
FXMVMS2025002CA5	Obstruction(s) to airflow	The return vent is blocked. It is recommended that the return vent have a minimum of three feet of clearance to facilitate air movement through the space.	25	administration	Yes
FXMVMS2025002CA6	Obstruction(s) to airflow	The return vent is blocked. It is recommended that the return vent have a minimum of three feet of clearance to facilitate air movement through the space.	22	administration	Yes
FXMVMS2025002CA7	Obstruction(s) to airflow	The return vent is blocked. It is recommended that the return vent have a minimum of three feet of clearance to facilitate air movement through the space.	21	administration	Yes
FXMVMS2025002CA8	Obstruction(s) to airflow	The return vent is blocked. It is recommended that the return vent have a minimum of three feet of clearance to facilitate air movement through the space.	17	administration	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXMVMS2025002CA9	Excessive stuffed animals	Stuffed animals were present and appear non-school issued. These items may house allergens if not properly maintained. Remove unnecessary materials or ensure teaching staff has and is following a cleaning schedule (launder or vacuum) since not the responsibility of custodial staff to clean non-school items.	17	administration	Yes
FXMVMS2025002CAA	Miscellaneous finding	Missing Lead Signage for: Slop sink Hand washing sinks Sprayer Faucet adjacent to 30	Kitchen	building	No
FXMVMS2025002CAB	Tight seal on ceiling tiles	Missing ceiling tiles. Ceiling tiles to be replaced to ensure tight seal.	85	custodial	Yes
FXMVMS2025002CAC	Excessive stuffed animals	Stuffed animals were present and appear non-school issued. These items may house allergens if not properly maintained. Remove unnecessary materials or ensure teaching staff has and is following a cleaning schedule (launder or vacuum) since not the responsibility of custodial staff to clean non-school items.	105	administration	Yes
FXMVMS2025002CAD	Obstruction(s) to airflow	The return vent is blocked. It is recommended that the return vent have a minimum of three feet of clearance to facilitate air movement through the space.	105	administration	Yes
FXMVMS2025002CAE	Miscellaneous finding	Missing lead signage.	106	building	No
FXMVMS2025002CAF	Air freshener/essential oils	Remind staff air fresheners, plug-ins, scent oil sticks, etc. are not permitted because they can mask an odor of concern and/or be an irritant to other individuals.	109	administration	Yes
FXMVMS2025002CB0	Excessive stuffed animals	Pillows and area rugs were present and appear non-school issued. These items may house allergens if not properly maintained. Remove unnecessary materials or ensure teaching staff has and is following a cleaning schedule (launder or vacuum) since not the responsibility of custodial staff to clean non-school items.	109	administration	Yes
FXMVMS2025002CB1	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The supply diffusers are visibly dirty and require dusting/cleaning.	108	custodial	Yes
FXMVMS2025002CB2	Obstruction(s) to airflow	The return vent is blocked. It is recommended that the return vent have a minimum of three feet of clearance to facilitate air movement through the space.	108	administration	Yes
FXMVMS2025002CB3	Miscellaneous finding	Missing lead signage for three outlets.	112	building	No
FXMVMS2025002CB4	General Cleanliness/Dust	Dead bugs observed in light fixture and require cleaning.	114	custodial	Yes
FXMVMS2025002CB5	General Cleanliness/Dust	Dead bugs observed in light fixture and require cleaning.	115	custodial	Yes
FXMVMS2025002CB6	Obstruction(s) to airflow	The return vent is blocked. It is recommended that the return vent have a minimum of three feet of clearance to facilitate air movement through the space.	111	administration	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXMVMS2025002CB7	Stained/damaged tiles	Stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile.	Outside 108	custodial	Yes
FXMVMS2025002CB8	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The supply diffusers are visibly dirty and require dusting/cleaning.	102	custodial	Yes
FXMVMS2025002CB9	Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)	A miniature refrigerator and microwave were observed. If not serving an educational purpose, these items are recommended to be removed to improve energy conservation.	93 Bathroom	administration	Yes
FXMVMS2025002CBA	Artificial plants/trees	Artificial plants easily collect dust (potential allergen) and are difficult to clean. This item is to be removed.	96	administration	Yes
FXMVMS2025002CBB	Air freshener/essential oils	Remind staff air fresheners, plug-ins, scent oil sticks, etc. are not permitted because they can mask an odor of concern and/or be an irritant to other individuals.	96	administration	Yes
FXMVMS2025002CBC	Miscellaneous finding	Lead signage missing from bathroom faucets.	92 & 95	building	No
FXMVMS2025002CBD	Plumbing fixture leaking/draining slowly	Cold water handle on the lab 2 faucet was leaking.	79	building	No
FXMVMS2025002CBE	Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA)	A coffee maker was observed. If not serving an educational purpose, these items are recommended to be removed to improve energy conservation.	69	administration	Yes
FXMVMS2025002CBF	Tight seal on ceiling tiles	Missing ceiling tiles. Ceiling tiles to be replaced to ensure tight seal.	74	custodial	Yes
FXMVMS2025002CC0	Miscellaneous finding	Missing lead signage.	1	building	No
FXMVMS2025002CC3	Artificial plants/trees	Artificial plants easily collect dust (potential allergen) and are difficult to clean. This item is to be removed.	4	administration	Yes
FXMVMS2025002CC4	Miscellaneous finding	Missing lead signage on bathroom faucet.	Bathroom between 9 & 10	building	No
FXMVMS2025002CC5	Miscellaneous finding	Missing lead signage on science classroom faucets.	Science classrooms 66, 68, 70, & 72	building	No
FXMVMS2025002CC6	Miscellaneous finding	Missing lead signage on three outlets.	Art Classroom 63	building	No