

# Findings for walkthrough Bushy Park Elementary School: November 4th, 2019

## (WXB PES2019000242)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXBPES20190013BE	Tight seal on ceiling tiles	Bubble in ceiling paint near front window.	202	building	No
FXBPES20190013C1	Tight seal on ceiling tiles	Stained ceiling tile back left	137	custodial	Yes
FXBPES20190013C2	Excessive stuffed animals		101	administration	Yes
FXBPES20190013C4	Tight seal on ceiling tiles	Minor crack in ceiling tile as soon as you walk in the art room door.	230	custodial	Yes
FXBPES20190013C5	Miscellaneous finding	Fire extinguisher needs to be inspected/signed off.	137	custodial	Yes
FXBPES20190013C7	Tight seal on ceiling tiles		100	custodial	Yes
FXBPES20190013C8	Electrical wiring exposed or disconnected wires		Closet c 12	building	No
FXBPES20190013C9	Tight seal on ceiling tiles		208	custodial	Yes
FXBPES20190013CA	Chemicals are capped	Storage height (fire code)	A37 Storage	administration	Yes
FXBPES20190013CC	Tight seal on ceiling tiles		211	custodial	Yes
FXBPES20190013CD	Tight seal on ceiling tiles		136	custodial	Yes
FXBPES20190013CE	Tight seal on ceiling tiles		114	custodial	Yes
FXBPES20190013CF	Miscellaneous finding	Cracks in corner walls	Stair 3	building	No
FXBPES20190013D1	Tight seal on ceiling tiles		119	custodial	Yes
FXBPES20190013D2	Tight seal on ceiling tiles		Hallway	custodial	Yes
FXBPES20190013D3	Exterior doors not fully sealed (daylight)		Gym Storage	building	No
FXBPES20190013D4	Tight seal on ceiling tiles		214	custodial	Yes
FXBPES20190013D5	Tight seal on ceiling tiles	Small stain on large tile when you walk in classroom.	224	custodial	Yes
FXBPES20190013D6	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	Dirt-Stained tiles near	Mini Auditorium	custodial	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXBPES20190013D8	Tight seal on ceiling tiles		126	custodial	Yes
FXBPES20190013D9	Tight seal on ceiling tiles		126	custodial	Yes
FXBPES20190013DA	Tight seal on ceiling tiles		133	custodial	Yes
FXBPES20190013DB	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	Supply vets dirty (high dusting)	cafeteria	administration	Yes
FXBPES20190013DD	Tight seal on ceiling tiles	Large crack in corner of wall before heading downstairs.	Stair 4	custodial	Yes
FXBPES20190013DE	Electrical outlets not secured, cover missing, frayed wires on equipment		221	building	No
FXBPES20190013DF	Miscellaneous finding	Crack on wall above drinking fountain	225	building	No
FXBPES20190013E0	Miscellaneous finding	Area around storm drain washing out	Exterior - back right corner	building	No
FXBPES20190013E2	Tight seal on ceiling tiles	Water stain on plastic ceiling tiles in elevator	Elevator	custodial	Yes
FXBPES20190013E3	Chemicals are capped	Storage height (fire code)	B39	administration	Yes
FXBPES20190013E5	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		200	administration	Yes
FXBPES20190013E6	Tight seal on ceiling tiles		Art storage hallway	custodial	Yes