Findings for walkthrough Phelps Luck Elementary School: February 25th, 2019 (WXPLES201900014C)

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------------|--|--|-----------|----------------|--------|
| FXPLES2019000A26 | Artificial plants/trees | Fake plant on desk. | A108 | administration | Yes |
| FXPLES2019000A27 | General Cleanliness/Dust | | A102A | custodial | Yes |
| FXPLES2019000A29 | Tight seal on ceiling tiles | | A129 | custodial | Yes |
| FXPLES2019000A2A | Tight seal on ceiling tiles | 2 ceiling tiles stained | A101B | custodial | Yes |
| FXPLES2019000A2B | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | A152 | administration | Yes |
| FXPLES2019000A2D | General Cleanliness/Dust | Dust on stage floor near cages, back wall. | Cafeteria | custodial | Yes |
| FXPLES2019000A30 | Tight seal on ceiling tiles | In kitchen area ceiling tiles near dishwasher sagging. Vent in that area rusted. Vents in back storage room room A121B dusty and ceiling tiles hanging. Employees working on dishwashing should make sure they turn on the exhaust fan while washing dishes. | Cafeteria | custodial | Yes |
| FXPLES2019000A31 | Artificial plants/trees | Artificial plants | A159 | administration | Yes |
| FXPLES2019000A33 | Tight seal on ceiling tiles | A130 | A167 | custodial | Yes |
| FXPLES2019000A34 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | A130 | A167 | administration | Yes |
| FXPLES2019000A38 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | Space heater | A164 | administration | Yes |
| FXPLES2019000A3A | General Cleanliness/Dust | Dusty vent in gym. High on wall. | Gym_A126 | custodial | Yes |
| FXPLES2019000A3B | General Cleanliness/Dust | Dusty on floor near gym storage area. | Gym_A126 | custodial | Yes |
| FXPLES2019000A3C | Tight seal on ceiling tiles | | A162 | custodial | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|---|----------|--------------------|--------|
| FXPLES2019000A3E | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | C108a | custodial | Yes |
| FXPLES2019000A40 | Tight seal on ceiling tiles | | C109 | custodial | Yes |
| FXPLES2019000A41 | General Cleanliness/Dust | Counters need cleaned. | B129 | custodial | Yes |
| FXPLES2019000A43 | General Cleanliness/Dust | Ants on counter near sink. | B130 | custodial | Yes |
| FXPLES2019000A44 | Excessive stuffed animals | | C110 | administration | Yes |
| FXPLES2019000A46 | Exterior doors not fully sealed (daylight) | Bottom of exterior door needs to be sealed. Snow and wind seep in. | C114 | building | Yes |
| FXPLES2019000A48 | Windows/Doors open | Window needs to be sealed. Wind comes in. | C114 | building | Yes |
| FXPLES2019000A49 | General Cleanliness/Dust | Counters need to be wiped daily. | B108 | custodial | Yes |
| FXPLES2019000A4C | Tight seal on ceiling tiles | One tile in closet has water damage. | C114 | custodial | Yes |
| FXPLES2019000A4D | Excessive stuffed animals | Fabric materials stuffed animals and chair pillows need cleaning plan | A157 | administration | Yes |
| FXPLES2019000A51 | Tight seal on ceiling tiles | Looks like tiles sag. | B113 | custodial | Yes |
| FXPLES2019000A52 | Tight seal on ceiling tiles | | B113 | custodial | Yes |
| FXPLES2019000A54 | Windows/Doors open | The exterior door has rust on the door frame. The closet door has peeling paint on the door frame. Hallway door also has peeling paint. | C114 | administration | Yes |
| FXPLES2019000A56 | Miscellaneous finding | Wall paint is peeling over sink. | C115 | | No |
| FXPLES2019000A58 | Artificial plants/trees | | B120 | administration | Yes |
| FXPLES2019000A59 | Tight seal on ceiling tiles | Ceiling tile outside classroom in hall is stained. | C116 | custodial | Yes |
| FXPLES2019000A5B | Plumbing fixture leaking/draining slowly | | C116 | custodial | Yes |
| FXPLES2019000A5C | General Cleanliness/Dust | Floor near desk is dusty. | B122-2 | custodial | Yes |
| FXPLES2019000A5D | Elevated moisture per moisture meter | | C116 | environmental | Yes |
| FXPLES2019000A5E | Elevated moisture per moisture meter | Stains on floor tiles under sink. If leak is still active, submit work order for plumbing. | C116 | building | Yes |
| FXPLES2019000A60 | Artificial plants/trees | | B122-2 | administration | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------------|--|--|-------------------|----------------|--------|
| FXPLES2019000A62 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | C104 | building | Yes |
| FXPLES2019000A63 | Miscellaneous finding | Light switch cover off wall in bathroom. | C105 | building | Yes |
| FXPLES2019000A65 | Air freshener/essential oils | | Back_C104_Hallway | administration | Yes |