IEQ SCHOOL DATA BASE									
School Name: ELLICOTT MILLS MS Principal: CAROL KETTERMAN DATE: 10.11.16							1		
IEQ Team Leader: CAROL KETTERMAN IEQ System Leader: Greg Maciulla									
LOOK-FORS	ROOM/LOCATION	COMMENTS	ADMIN	FACILITIES	WORK ORDER NUMBER of POTENTIAL IEQ	DATE ASSIGNED	COMPLETION DATE	30 DAY REVISIT	CLOSED
No unusual or offensive odors or temperature discomfort	55. 18.	Smell but can't find source. 18-smell from air unit.		IEQ WO to HVAC					
2. No Air Fresheners	116. 19.	116-spray in restroom. 19-air freshner/honeywell.	X						
3. No food, dirty lunch boxes, etc. left in room	127. 20,28,25,35,14.	127-food. 20-food, water bottles. 28-green food. 25-food. 35-water container/bottles, open candy container. 14-food, closet-cookies & food.	X						
4. Vents are clean and unobstructed	122,1. 69,63,64. 16,29,37,15.	122-vents blocked. 1-we moved books. 69-difusers dirty. 63-wood dust in difuser (tech ed). 16-air unit vent, cap down. 28-green food. 29-loose vent cap. 37-blocked air by file cabinet. 15-air unit needs cleaning.	X	REGULAR WO to HVAC					
5. Temperature sensors are not blocked									
6. Area appears clean and dust free	All science rooms. 117, 122,107,telacommunications room,2,3,105,112,113,114,116,110,20,art room,media,104,102,media production,127,electical room,elevator room,129 closet. 63. 16, 17,18,20,28	dusty (custodial office). Clear under sinks (custodial office). 107-clear light lens (custodial office). Telecommunications room-raceway dusty (custodial office). 2-dusty shelf (custodial office). 3-dusty (custodial office). 105-dusty (custodial office). 113-dusty & bucket of sand (custodial office). 114,116,110,20-dusty (custodial office). Art room-clear out under sink (custodial office). Media-dusty shelves (custodial office). 104,102,127,electrical room-dusty (custodial office). Media production-clutter (Admin). Elevator room-floor dirty (custodial office). 129 closet-dirty floor (custodial office). 129 closet-potting soil-needs to be removed or put in a sealed container (Admin). 63-not cleaned at end of day (tech ed). 16-sodas. 17-dust due to items on ledges. 18-clean lamp. 20-dust on cabinets due to clutter. 112-pencils in drain, sink 2, check all (building maintanence).	X	REGULAR WO to PLUMBING					
7. No signs of animal infestation									
8. Ceiling tiles present; no broken, stained, or painted	103,98,107,1,113,116. Foyer entry near 67, RR of 65,63,64,59, hall out of 57, closet in health suite. 20,33,14,15.	103-2. 98-2. 107-2 small stains. 1-1 small euv. 113-2 stain. 116-restroom, 1 stain. Foyer entry near 67-tile out of place. 63-stain, 64-lots of stains,65-stain ceiling tile around exhaust. 20-loose ceiling tile & ceiling stain. 28-dirty counter. 33-stained red ceiling tiles. 14-dusty ceiling tiles. 15-loose ceiling tile. CUSTODIANS SHOULD REPLACE FULL CEILING TILES		REGULAR WO to CARPENTRY ceiling tiles that need to be cut					
9. Walls show no signs of water damage/mildew/ paint irregularities	29	29-cracked wall @ ceiling.		REGULAR WO to HARDWARE					

IEQ SCHOOL DATA BASE								
School Name: ELLICOTT	MILLS MS	Principal: CAROL KETTERMAN DATE: 10.11.16						
IEQ Team Leader: CAROL KETTERMAN		IEQ System Leader: Greg Maciulla						
10. No condensation or other evidence of humidity on ceilings, walls, doors, etc.								
11. Limited use of non-issued HCPSS furniture and appliances	44,71. 25,31.	41 & 71-microwave & mini refrigerator. 25-heater/fan. 31-microwave, shed box.	X					
12. No excessive fabric materials, stuffed animals, beanbags, pillows, etc.	98. 51. 16,17,33,14.	98. 51-throw rug. 16-stuffed animals. 17-flags, clutter, cover for stool. 33-stuffed animals. 14-fake plants.	X					
13. No structural or physical gaps around exit doors								
14. No improperly stored materials/chemicals	981,270.11	98, 127. 11-cleaning products.						
15. Floor coverings are level and secure (tile, carpets, wood board, etc.)	Art room. Staff lounge. 17,11,28,29,25,33,15.	Art room-replace missing floor tile under sink (bulding maintenance). Staff lounge-carpet heavily stained. 17-stained carpet. 11-red carpet stain. 28-stained floor tiles. 29-cracked floor tile, missing floor tile. 25-stained carpet tile. 33-stained carpet. 15-stained carpet.						
16. Barrier mats vacuumed well	73, teachers lounge, admin area.	All-carpets stained.	X					
17. Fish tanks are clean and located away from vents/thermostats								
18. Waterproof barriers in place for plants and no standing water	122	122-plant leaf dropping.	X					
19. Sinks and fountains drain quickly and work properly including absence of leaks	117,121,109,108,103.38	117-drip under sink (2). (7)-clogged sink. 38-leak under sink.		REGULAR WO to PLUMBING				
20. No standing water in sinks, fountains, on counter								
21. Carpet dry nearby sinks, fountains	109,108,103.00	109-stain carpet. 108-stain carpet. 103.	X					

		IEQ SCHOOL DATA BASE	<u> </u>						
School Name: ELLICOTT MILLS MS Principal: CAROL KETTERMAN DATE: 10.11.16									
IEQ Team Leader: CAROL	KETTERMAN	IEQ System Leader: Greg Maciulla							
22. Soap and paper towels available	Art room. 36.	Art room-replace broken foam soap dispenser (custodial office). 36-dish soap.	X						
23. All electrical outlets secure, no frayed wires on equipment	52,31.	52-light cap. 31-light cap down in closet, electrical outlet on floor.		REGULAR WO to ELECTRICAL					
24. All electrical cords secured and not extending across walkways	1.53.	53-cord across floor/no barrier cover.	X						
25. No extension cords used as permanent wiring	71. 13.	71-electric strip used to plug in mini refrigerator and microwave. 13-no power strips.	X						
26. No electrical equipment near sinks or source of water									
27. No exposed disconnected wires	73	73-data jack out of wall.		REGULAR WO to IT					
ADJACENT SCH	OOL GROUNDS								
LOOK-FORS	ROOM/LOCATION	COMMENTS	ADMIN	FACILITIES	COMMENTS/W ORK ORDER	ASSIGNED TO	COMPLETION DATE	30 DAY REVISIT	CLOSED
28. No litter						- 10	2.112	112 (121	
29. No large insect populations (wasps, bees)									
30. Awnings secure, no leaks									
31. Shrubbery not near vents or windows which can be opened									
32. Trees do not provide access to roof									
33. No broken windows									
34. Windows are closed									
35. Exterior doors are closed									

IEQ SCHOOL DATA BASE								
School Name: ELLICOTT MILLS MS	Principal: CAROL KETTERMAN	DATE: 10.11.16						
IEQ Team Leader: CAROL KETTERMAN	IEQ System Leader: Greg Maciulla							
36. No pools of standing/stagnant water								
37. Exterior veneer intact								
38. Outside lights working and intact								
39. Gutters and downspouts clear/working								
40. No stains from roof on outside walls								
41. Bins from garbage and recycling clearly marked								
42. Hard surfaces (sidewalks, etc.) cleared of any turf application 43. Proper maintenance or planted beds and other								
44. Landscaping and turf look healthy and disease free								
	r-repair HVAC grill (building maintenance). Art room-fire exit not done for isafe. (Electrical office-WO). TP 2-light bulbs in closet. 29-remove books & o	=	=					