



May 22, 2018

Howard County Public School System
9020 Mendenhall Ct
Suite C
Columbia, MD 21045

Attn: Mr. Scott Washington
Director of School Construction
(scott_washington@hcpss.org)

Subject: Post Remediation Inspection
Oakland Mills Middle School
9540 Kilimanjaro Road
Columbia, Maryland 21045

Mr. Washington,

Soil and Land Use Technology, Inc. (SaLUT) conducted post-remediation inspections at Oakland Mills Middle School located at 9540 Kilimanjaro Road, Columbia, Maryland 21045 on December 4, 2017, and January 5, 2018. The inspection included a visual observation for the remediated areas listed below:

- 1 - HVAC units mechanical room
- 2 - AC diffusers throughout the building
- 3 - Exhaust fans near HVAC intake, and
- 4 - Roof drain strainers.

The results of SaLUT's inspection concluded that the remediation project had been acceptably completed.

We appreciate the opportunity to provide industrial hygiene services for HCPSS. Should you have any questions, please do not hesitate to contact us.

Sincerely,

Azzam Jawad
Project Manager