| Timestamp            | Observation:                                  | Room Number or<br>Location/Name: | Comments for this room:                 | CUSTODIAL | FACILITIES WORK ORDERS | ADMINISTRATION | IEQ WORK ORDERS | ASSIGNED DATE | COMPLETION DATE | 30-DAY REVISIT | CLOSED |
|----------------------|---|----------------------------------|---|-----------|------------------------|----------------|-----------------|---------------|-----------------|----------------|--------|
| 5/17/2017 11:03:18   | 02. AIR FRESHENERS                            | 3                                | Spray                                   |           |                        | Х              |                 |               |                 |                |        |
|                      | 03. FOOD: Unsealed,                           |                                  |   |           |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:06:34   | left in room, dirty lunch boxes               | 87                               | Container                               |           |                        | X              |                 |               |                 |                |        |
|                      | 03. FOOD: Unsealed,                           |                                  |   |           |                        | .,             |                 |               |                 |                |        |
| 5/17/2017 10:20:09   | left in room, dirty lunch                     | 23                               | Container                               |           |                        | X              |                 |               |                 |                |        |
| 3/1//2017 10.20.09   | 04: VENTS: Dirty,                             | 25                               | Container                               |           |                        |                |                 |               |                 |                |        |
|                      | obstructed (Wall,                             |                                  |   | ×         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:11:42   |   | 91                               | Dusty                                   |           |                        |                |                 |               |                 |                |        |
|                      | 04: VENTS: Dirty,                             |                                  |   | ,,        |                        |                |                 |               | 5/47/47         |                |        |
| 5/17/2017 10:45:45   | obstructed (Wall,                             | 103 dry storage                  | Clean vents                             | X         |                        |                |                 |               | 5/17/17         |                |        |
| 0/11/2017 10.40.40   | 06: CLEANLINESS:                              | 100 dry storage                  | Olcan vents                             |           |                        |                |                 |               |                 |                |        |
| 5/17/2017 9:58:45    |   | 16                               | Clutter                                 | X         |                        |                |                 |               |                 |                |        |
|                      | 06: CLEANLINESS:                              |                                  |   | Х         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:02:26   | , , , , , , , , , , , , , , , , , , ,         | 18                               | Declutter team closet                   | ^         |                        |                |                 |               |                 |                |        |
| F (47/0047 40-44-40  | 06: CLEANLINESS:                              | 0.5                              | Ol. Har                                 | ×         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:14:46   | 06: CLEANLINESS:                              | 95                               | Clutter                                 |           |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:15:30   |   | 14                               | Rags in metal tin.                      | X         |                        |                |                 |               |                 |                |        |
| 0/11/2017 10:10:00   | 06: CLEANLINESS:                              |                                  | Dust on ledges to roof                  | .,        |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:18:22   |   | 93                               | Windows - high dusters                  | X         |                        |                |                 |               |                 |                |        |
|                      |   |                                  | Closet door must be                     |           |                        |                |                 |               |                 |                |        |
| E/47/2047 40:20:47   | 06: CLEANLINESS:                              | 440                              | able to open. Clutter                   | X         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:22:47   | 06: CLEANLINESS:                              | 113                              | needs to be removed.                    |           |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:27:06   |   | 24                               | Declutter closet and desk area.         | ×         |                        |                |                 |               |                 |                |        |
|                      | 06: CLEANLINESS:                              |                                  |   | .,        |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:30:17   |   | 24                               | Declutter declutter                     | X         |                        |                |                 |               |                 |                |        |
|                      | 06: CLEANLINESS:                              |                                  | High dusters needed on                  | Х         | 32233                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:30:32   | · ·   | 100                              | duct work                               | ^         | 02200                  |                |                 | 0/20/11       |                 |                |        |
| 5/17/2017 10:40:06   | 06: CLEANLINESS:                              | Access to boiler room            | Decling point                           | ×         | 32221                  |                |                 | 5/25/17       |                 |                |        |
| 3/11/2017 10.40.00   | 06: CLEANLINESS:                              | Access to boller room            | Peeling paint                           |           |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:42:28   |   | 33                               | Chair blocking door                     | X         |                        |                |                 |               |                 |                |        |
|                      | 06: CLEANLINESS:                              |                                  | Cart by the exit door                   | V         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:43:10   | Dust, trash                                   | 33                               | door                                    | Х         |                        |                |                 |               |                 |                |        |
|                      | 06: CLEANLINESS:                              |                                  | Set of tables blocking                  | X         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:48:00   | Dust, trash                                   | 38                               | the door                                |           |                        |                |                 |               |                 |                |        |
|                      | 06: CLEANLINESS:                              |                                  | Tables need to be moved for proper exit | x         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:48:07   |   | 33                               | walkway                                 | _ ^       |                        |                |                 |               |                 |                |        |
|                      | 06: CLEANLINESS:                              |                                  | Clutter, bag of dirt by                 | Х         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:57:31   | ,   | 47                               | exit door                               | ^         |                        |                |                 |               |                 |                |        |
|                      | 08: CEILING TILES:<br>Stained, broken, holes, |                                  | Stained and loose tiles                 | ×         | 32222                  |                |                 | 5/25/17       | 5/30/17         |                |        |
| 5/17/2017 9:53:35    |   | 81                               | and escutcheon                          | _ ^       | 32222                  |                |                 | 3/23/17       | 3/30/17         |                |        |
|                      | 08: CEILING TILES:                            |                                  |   |           |                        |                |                 |               |                 |                |        |
| E/4=/00 := 5 = : : : | Stained, broken, holes,                       | ,-                               | All good                                | X         |                        |                |                 |               |                 |                |        |
| 5/17/2017 9:54:41    | '   | 15                               |   |           |                        |                |                 |               |                 |                |        |
|                      | 08: CEILING TILES:<br>Stained, broken, holes, |                                  | Stained tiles and rust at               | x         | 32229                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 9:57:16    |   | 79                               | AHU                                     | _ ^       | 02223                  |                |                 | 5/25/17       |                 |                |        |
|                      | 08: CEILING TILES:                            |                                  | Stained tile. 1 marked 1                |           |                        |                |                 |               |                 |                |        |
| E/47/0047 0:50 00    | Stained, broken, holes,                       | 50                               | not marked                              | Х         | 32245                  |                |                 | 5/25/17       | 5/25/17         |                |        |
| 5/17/2017 9:59:30    | ļ'  | 58                               |   |           |                        |                |                 |               |                 |                | -      |
|                      | 08: CEILING TILES:<br>Stained, broken, holes, |                                  |   | x         | 32236                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:00:53   |   | Hallway next to gym              | Several hole tiles                      | · ``      |                        |                |                 | 5.25,17       |                 |                |        |

| Timestamp          | Observation:  | Room Number or<br>Location/Name: | Comments for this room:  | CUSTODIAL | FACILITIES WORK ORDERS | ADMINISTRATION | IEQ WORK ORDERS | ASSIGNED DATE | COMPLETION DATE | 30-DAY REVISIT | CLOSED |
|--------------------|---|----------------------------------|--|-----------|------------------------|----------------|-----------------|---------------|-----------------|----------------|--------|
| 5/17/2017 10:01:58 | 08: CEILING TILES:<br>Stained, broken, holes,<br>painted  | 112                              | Stained tile   | x         | 32241                  |                |                 | 5/25/17       | 5/30/17         |                |        |
| 5/17/2017 10:03:03 | 08: CEILING TILES:<br>Stained, broken, holes,<br>painted  | Foyer to 87                      | Stained and painted tiles  | х         | 32242                  |                |                 | 5/25/17       | 5/30/17         |                |        |
| 5/17/2017 10:04:23 | 08: CEILING TILES:<br>Stained, broken, holes,<br>painted  | 108                              | Cracked tile   | Х         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:04:55 | 08: CEILING TILES:<br>Stained, broken, holes,<br>painted  | 87                               | Stained tiles and painted  | х         | 32253                  |                |                 | 5/25/17       | 5/30/17         |                |        |
| 5/17/2017 10:10:39 | 08: CEILING TILES:<br>Stained, broken, holes,<br>painted  | 5th grade boys bathroom          | Cracked/broken light cover   | х         | 32249                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:15:35 | 08: CEILING TILES:<br>Stained, broken, holes,   | 13                               | Sprinkler ring missing   | х         | 32250                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:16:50 | 08: CEILING TILES:<br>Stained, broken, holes,   | 57                               | Tile above circulation desk has stain                                    | х         | 32244                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:16:55 | 08: CEILING TILES:<br>Stained, broken, holes,   | 93                               | Stained roof leak  | х         | 32252                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:23:10 | 08: CEILING TILES:<br>Stained, broken, holes,   | 97                               | Stain at EXIT sign   | х         | 32254                  |                |                 | 5/25/17       | 5/26/17         |                |        |
|                    | 08: CEILING TILES:<br>Stained, broken, holes,<br>painted  | Front entrance                   | Stained and misplaced tiles  | Х         |                        |                |                 |               |                 |                |        |
|                    | 08: CEILING TILES:<br>Stained, broken, holes,<br>painted  | 24                               | Ceiling tile stain in bathroom, has already notified through school dude | х         | 32247                  |                |                 | 5/25/17       | 5/30/17         |                |        |
| 5/17/2017 10:40:02 | 08: CEILING TILES:<br>Stained, broken, holes,   | Access to boiler room            | Ceiling tiles-holes  | х         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:43:53 | 08: CEILING TILES:<br>Stained, broken, holes,   | 103-kitchen dish area            | Hole at escutcheon   | х         | 32255                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:51:05 | 08: CEILING TILES:<br>Stained, broken, holes,<br>painted  | 5                                | Stained and painted tile   | Х         | 32258                  |                |                 | 5/25/17       | 5/30/17         |                |        |
| 5/17/2017 10:51:46 | 08: CEILING TILES:<br>Stained, broken, holes,<br>painted  | 38                               | Stains on two tiles near window  | х         | 32259                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 11:01:01 | 08: CEILING TILES:<br>Stained, broken, holes,<br>painted  | 3                                | Stained and painted tiles  | х         | 32260                  |                |                 | 5/25/17       | 5/31/17         |                |        |
| 5/17/2017 11:07:33 | 08: CEILING TILES:<br>Stained, broken, holes,   | 1                                | Stained and misplaced  | х         | 32261                  |                |                 | 5/25/17       | 5/30/17         |                |        |
|                    | 08: CEILING TILES:<br>Stained, broken, holes,   | 2                                | Ceiling tile stained no pin and roof leak red pin                        | х         |                        |                |                 |               |                 |                |        |
|                    | 08: CEILING TILES:<br>Stained, broken, holes,   | 31                               | Declutter top of cabinetneed 18 inches                                   |           |                        | Х              |                 |               |                 |                |        |
|                    | 09. WATER DAMAGE:<br>Spotting, mildew, paint<br>irregularities (ceilings,<br>walls, doors, windows) | 87                               | Windows rusted and salted  |           | 32264                  |                |                 | 5/25/17       |                 |                |        |

| Timestamp          | Observation:   | Room Number or<br>Location/Name: | Comments for this room:                                 | CUSTODIAL | FACILITIES WORK ORDERS | ADMINISTRATION | IEQ WORK ORDERS | ASSIGNED DATE | COMPLETION DATE | 30-DAY REVISIT | CLOSED |
|--------------------|--|----------------------------------|---|-----------|------------------------|----------------|-----------------|---------------|-----------------|----------------|--------|
| 5/17/2017 9:50:09  | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | 71                               | Fridge  |           |                        | ×              |                 |               |                 |                |        |
| 5/17/2017 10:34:06 | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | 31                               | Non Howard county furnituretable, two chairs            |           |                        | ×              |                 |               |                 |                |        |
| 5/17/2017 10:41:29 | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | Custodial                        | Fans  |           |                        | х              |                 |               |                 |                |        |
| 5/17/2017 10:43:40 | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | 33                               | Blue Desk chair   |           |                        | х              |                 |               |                 |                |        |
| 5/17/2017 10:46:03 | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | 36                               | Overhead chair and black and white chairs               |           |                        | х              |                 |               |                 |                |        |
| 5/17/2017 10:48:52 | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | 103                              | Fans  |           |                        | х              |                 |               |                 |                |        |
| 5/17/2017 10:49:24 | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | 38                               | Not able to access hcpss cabinetlock on door.           |           |                        | х              |                 |               |                 |                |        |
| 5/17/2017 10:55:52 | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | 46                               | File cabinets,<br>bookcases, rocking chair<br>and stool |           |                        | х              |                 |               |                 |                |        |
| 5/17/2017 10:56:22 | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | 7                                | Shelf   |           |                        | х              |                 |               |                 |                |        |
| 5/17/2017 10:58:37 | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | 6                                | Broken rocker   |           |                        | х              |                 |               |                 |                |        |
| 5/17/2017 11:01:50 | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | 3                                | Shelves   |           |                        | х              |                 |               |                 |                |        |
|                    | 11. NON-ISSUED<br>HCPSS FURNITURE<br>AND APPLIANCES  | 2                                | Shelf   |           |                        | х              |                 |               |                 |                |        |
| 5/17/2017 10:12:01 | 12. FABRIC<br>MATERIALS: Stuffed<br>animals, beanbags,<br>pillows, blankets, rugs,<br>etc. | 18                               | Red fabric needs to be removed.                         |           |                        | х              |                 |               |                 |                |        |
| 5/17/2017 10:17:18 | 12. FABRIC<br>MATERIALS: Stuffed<br>animals, beanbags,<br>pillows, blankets, rugs,<br>etc. | 28                               | Remove fabric on cabinet and fabric on table.           |           |                        | х              |                 |               |                 |                |        |
|                    | 12. FABRIC<br>MATERIALS: Stuffed<br>animals, beanbags,<br>pillows, blankets, rugs,         |                                  |   |           |                        | ×              |                 |               |                 |                |        |
| 5/17/2017 10:18:13 | etc.  12. FABRIC MATERIALS: Stuffed animals, beanbags, pillows, blankets, rugs.            | 28                               | Fake flower, plastic fruit  Rug, pillows, stuffed       |           |                        | x              |                 |               |                 |                |        |
| 5/17/2017 10:24:30 | etc.   | 97                               | animals   |           |                        |                |                 |               |                 |                |        |
|                    | 12. FABRIC<br>MATERIALS: Stuffed<br>animals, beanbags,<br>pillows, blankets, rugs,         |                                  |   |           |                        | x              |                 |               |                 |                |        |
| 5/17/2017 10:53:59 |  | 5 storage                        | Bean bag  |           |                        |                |                 |               |                 |                |        |

| Timestamp          | Observation:   | Room Number or<br>Location/Name: | Comments for this room:                                | CUSTODIAL | FACILITIES WORK ORDERS | ADMINISTRATION | IEQ WORK ORDERS | ASSIGNED DATE | COMPLETION DATE | 30-DAY REVISIT | CLOSED |
|--------------------|--|----------------------------------|--|-----------|------------------------|----------------|-----------------|---------------|-----------------|----------------|--------|
|                    | 12. FABRIC<br>MATERIALS: Stuffed<br>animals, beanbags,<br>pillows, blankets, rugs,<br>etc. | 7                                | Stuffed animals, rugs, and lanterns, fabricated stools |           |                        | х              |                 |               |                 |                |        |
|                    | 12. FABRIC<br>MATERIALS: Stuffed<br>animals, beanbags,<br>pillows, blankets, rugs,         |                                  |  |           |                        | х              |                 |               |                 |                |        |
| 5/17/2017 11:09:54 | etc.  13. AIR GAPS: Structural or physical gaps around exit doors                          | 79                               | Pom Poms  Visible daylight                             |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
|                    | 13. AIR GAPS:<br>Structural or physical<br>gaps around exit doors                          | Doors in hallway next to gym     | Daylight   |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
|                    | 13. AIR GAPS:<br>Structural or physical<br>gaps around exit doors                          | 87                               | Daylight   |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:15:59 | 13. AIR GAPS:<br>Structural or physical<br>gaps around exit doors                          | 93                               | Daylight   |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:20:59 | 13. AIR GAPS:<br>Structural or physical<br>gaps around exit doors                          | 97                               | Daylight   |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:35:26 | 13. AIR GAPS:<br>Structural or physical<br>gaps around exit doors                          | 100                              | Daylight   |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
|                    | 13. AIR GAPS:<br>Structural or physical<br>gaps around exit doors                          | Reading recovery room            | Duplicatedelete other entry for door                   |           | X                      |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 11:01:52 | 13. AIR GAPS:<br>Structural or physical<br>gaps around exit doors                          | 3                                | Daylight   |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 11:06:43 | 13. AIR GAPS:<br>Structural or physical<br>gaps around exit doors                          | 1                                | Rust   |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 11:15:30 | 13. AIR GAPS:<br>Structural or physical<br>gaps around exit doors                          | Exterior door storage            | Daylight   |           | 32265                  |                |                 | 5/25/17       |                 |                |        |
|                    | 15. FLOORS:<br>Coverings not level or<br>secure (tile, carpets,<br>wood board, etc.)       | Hallway near<br>guidance         | Tiles separating                                       |           | 32269                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:27:53 | 15. FLOORS:<br>Coverings not level or<br>secure (tile, carpets,<br>wood board, etc.)       | Adult women across from office   | Floor drain cover                                      |           | 32270                  |                |                 | 5/25/17       |                 |                |        |
|                    | 18. PLANTS: NO<br>ARTIFICIAL. LIVE -<br>Waterproof barriers in                             | 28                               | Live flower has been its timeno water container        |           |                        | х              |                 |               |                 |                |        |
|                    | 18. PLANTS: NO<br>ARTIFICIAL. LIVE -<br>Waterproof barriers in                             | 97                               | Flowers  |           |                        | х              |                 |               |                 |                |        |
|                    | 19. SINKS AND<br>FOUNTAINS: Drain<br>slowly, work improperly,                              |                                  | ADA padding at sink                                    |           | 32270                  |                |                 | 5/25/17       |                 |                |        |

| Timestamp          | Observation:  | Room Number or<br>Location/Name: | Comments for this room:                           | CUSTODIAL | FACILITIES WORK ORDERS | ADMINISTRATION | IEQ WORK ORDERS | ASSIGNED DATE | COMPLETION DATE | 30-DAY REVISIT | CLOSED |
|--------------------|---|----------------------------------|---|-----------|------------------------|----------------|-----------------|---------------|-----------------|----------------|--------|
| 5/17/2017 10:43:53 | 19. SINKS AND<br>FOUNTAINS: Drain<br>slowly, work improperly,<br>leak                   | 103 dishwas                      | Water leak at<br>dishwasher discharge             |           | ×                      |                |                 |               |                 |                |        |
| 5/17/2017 11:07:32 | 19. SINKS AND<br>FOUNTAINS: Drain<br>slowly, work improperly,<br>leak                   | 5                                | Drains blocked on both sinks                      |           | 32272                  |                |                 | 5/25/17       | 5/30/17         |                |        |
| 5/17/2017 10:32:12 | 23. ELECTRICAL:<br>Electrical outlets not<br>secured, cover missing,<br>frayed wires on | Roof access                      | Water in light lenses                             |           | 32273                  |                |                 | 5/25/17       | 5/30/17         |                |        |
|                    | 26. ELECTRICAL EQUIPMENT: Near sinks or source of water                                 | 91                               | Blocked needs cleared out                         | ×         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:33:39 | 26. ELECTRICAL<br>EQUIPMENT: Near<br>sinks or source of water                           | Stage                            | 3' clearance                                      | х         |                        |                |                 |               |                 |                |        |
| 5/17/2017 9:54:16  | 28. LITTER  | 15                               | Clutter in the corner                             | Х         |                        |                |                 |               |                 |                |        |
| 5/17/2017 10:37:15 | 33. WINDOWS: Broken   | 38                               | Hole in exterior window                           |           | 32278                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:05:48 | 35. EXTERIOR DOORS:<br>Not closed   | 20                               | Gap under exterior door                           |           | 32300                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:09:04 | 35. EXTERIOR DOORS:<br>Not closed   | 21                               | Desk blocking exit                                |           |                        | X              |                 |               |                 |                |        |
|                    |   |                                  | Small hole in the bottom left of the door         |           | 32268                  |                |                 |               |                 |                |        |
| 5/17/2017 10:09:30 | +   | 21                               |   |           | 02200                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:40:39 |   | 23                               | Door frame rusted hole                            |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:45:32 | 35. EXTERIOR DOORS:<br>Not closed<br>35. EXTERIOR DOORS:                                | 15                               | Hole rusted in door frame  2 holes rusted in both |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:47:03 | Not closed  | 51                               | sides of door frame                               |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:48:18 |   | 47                               | Holes rusted in door frame                        |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:55:18 |   | 79                               | Hole in door frame                                |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:59:19 |   | 6                                | Rusted out  |           | 32268                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:28:48 |   | 24                               | Exterior wall is exposed from the classroom.      |           | 32280                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:39:10 | 37. EXTERIOR VENEER: Exterior wall damaged  | 31                               | Sidewalk damage at door                           |           | 32286                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:53:13 | 37. EXTERIOR<br>VENEER: Exterior wall<br>damaged  | 93                               | Wall damaged at base.<br>Bricks missing           |           | 32282                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:43:48 | 42. PAVEMENT:<br>Damaged, failing,<br>missing   | 17                               | 8" drop off soil washed away                      |           | 32287                  |                |                 | 5/25/17       |                 |                |        |
| 5/17/2017 10:44:40 | 42. PAVEMENT:<br>Damaged, failing,  | 15                               | Hole at door on sidewalk                          |           | 32268                  |                |                 | 5/25/17       |                 |                |        |