

Findings for walkthrough Clarksville Middle School: July 5th, 2023 (WXXCMS202300046F)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXCMS20230023A2	Miscellaneous finding	Thermostat display blank and the air conditioning does not seem to be running. The inside temperature is 88 degrees Fahrenheit (F).	Portables # 235	building	Yes
FXXCMS20230023A3	Miscellaneous finding	Thermostat cooling set point set at 74 degrees F. Per the HCPSS Summer Operation Schedule, the set point is to be 82 degrees F.	Portables # 39	building	Yes
FXXCMS20230023A4	Stained/damaged tiles	Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile.	Staff Lounge	custodial	Yes
FXXCMS20230023A5	Stained/damaged tiles	Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile.	Classroom 32	custodial	Yes
FXXCMS20230023A6	Stained/damaged tiles	Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile.	Office 9A inside classroom 9	custodial	Yes
FXXCMS20230023A7	Stained/damaged tiles	Water stained ceiling tile. If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile.	Classroom 11	custodial	Yes
FXXCMS20230023A8	Stained/damaged tiles	Water stained ceiling tile (near supply diffuser). If not already being addressed, school custodial staff is to submit a work order to Building Maintenance to evaluate, correct source, and replace ceiling tile.	Hallway near classroom 32 connecting front of the building and back	custodial	Yes
FXXCMS20230023A9	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The return air grille is visibly dirty and requires dusting/cleaning.	Classroom 32	custodial	Yes

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXCMS20230023AA	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The supply diffusers are visibly dirty and require dusting/cleaning.	Classroom 61-modular section	custodial	Yes
FXXCMS20230023AB	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The supply diffusers are visibly dirty and require dusting/cleaning.	Classroom 62-modular section	custodial	Yes
FXXCMS20230023AC	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	The supply diffusers are visibly dirty and require dusting/cleaning.	Classroom 64-modular section	custodial	Yes
FXXCMS20230023AD	Relative humidity above 70%	Relative humidity 79%. Building Maintenance (HVAC) to deliver dehumidifiers during period of outdoor high humidity/dew point. The Office of the Environment understands Building Maintenance is planning a modification to the HVAC units that serve the modular, however this has not been completed to date.	Classroom 62-modular section	building	Yes
FXXCMS20230023AE	Relative humidity above 70%	Relative Humidity at 70% at the time of taking the reading. Building Maintenance (HVAC) to deliver dehumidifiers during period of outdoor high humidity/dew point. The Office of the Environment understands Building Maintenance is planning a modification to the HVAC units that serve the modular, however this has not been completed to date.	Classroom 61-modular section	building	Yes
FXXCMS20230023AF	Uncomfortable temperature	Space is being overcooled and maintaining 74 degrees F.	Classroom 64-modular section	building	Yes
FXXCMS20230023B0	Uncomfortable temperature	Space is being overcooled and maintaining 74 degrees F.	Classroom 63-modular section	building	Yes
FXXCMS20230023B1	Uncomfortable temperature	Space is being overcooled and maintaining 72 degrees F and no computers present.	Computer Lab #30 inside media center	building	Yes
FXXCMS20230023B2	Miscellaneous finding	Entire gym empty and not being used and the lights off but the HVAC system was running.	Gym	building	Yes
FXXCMS20230023F3	Miscellaneous finding	Air conditioning running in unoccupied spaces.	Multiple unoccupied Spaces	building	Yes