

# Findings for walkthrough Oakland Mills High School: September 30th, 2023

## (WXOMHS20230004D0)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXOMHS2023002703	Visible mold on surfaces due to elevated relative humidity/dew point		Rooms 108, 103, 106, 801, 210, 805, 270, Media Lab, 308, 701 and 606	environmental	Yes