

# Findings for walkthrough Oakland Mills High School: September 30th, 2023

## (WXOMHS20230004D9)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXOMHS2023002719	Visible mold on surfaces due to elevated relative humidity/dew point		404	environmental	Yes