

Findings for walkthrough Laurel Woods Elementary School: December 7th, 2018 (WXLWES20180000D9)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXLWES201800046E	Visible mold on surfaces due to elevated relative humidity/dew point		Room 68	environmental	Yes