

Findings for walkthrough Talbott Springs Elementary School: November 2nd, 2018 (WXTSES20180000DE)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXTSES2018000518	Visible mold on surfaces due to elevated relative humidity/dew point		Room 28	environmental	Yes