

Findings for walkthrough Dayton Oaks Elementary School: December 3rd, 2018

(WXDOES20180000EB)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXDOES201800054D	Plumbing fixture leaking/drain	ing slowly	A87, A90, B02, C07, C08, C09, and D02	building	Yes