

Findings for walkthrough Dayton Oaks Elementary School: December 3rd, 2018 (WXDOES20180000EB)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXDOES201800054D	Plumbing fixture leaking/draining slowly		A87, A90, B02, C07, C08, C09, and D02	building	Yes