

Findings for walkthrough Bryant Woods Elementary School: January 8th, 2019 (WXBWES20190000F6)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXBWES201900062B	Air freshener/essential oils		146	administration	Yes
FXBWES201900062C	Chemicals are capped	Kitchen storage closet - height of materials (fire code)	Kitchen	administration	Yes
FXBWES201900062E	Tight seal on ceiling tiles	Ceiling tile not aligned in gym storage	gym	custodial	Yes
FXBWES2019000630	Artificial plants/trees		Staff Restroom	administration	Yes
FXBWES2019000631	Artificial plants/trees		Staff Lounge	administration	Yes
FXBWES2019000632	Chemicals are capped	Storage height	Records Room	administration	Yes
FXBWES2019000634	Tight seal on ceiling tiles	Stained ct - media	124	custodial	Yes
FXBWES2019000636	Tight seal on ceiling tiles	Stainedned Tile near ceiling mounted unit	123	custodial	Yes
FXBWES2019000638	Chemicals are capped	Storage height	Storage near 132	administration	Yes
FXBWES201900063A	Excessive stuffed animals	Curtains and materials hanging from ceiling (fire Marshall)	127	administration	Yes
FXBWES201900063C	Miscellaneous finding	Exit light out	102		No
FXBWES201900063E	Tight seal on ceiling tiles		101	custodial	Yes
FXBWES201900063F	Tight seal on ceiling tiles		103	custodial	Yes
FXBWES2019000640	Miscellaneous finding	Light out	Front Hallway		No
FXBWES2019000642	Miscellaneous finding	Light cover coming down	109		No
FXBWES2019000644	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress	Vent needs repair	110	administration	Yes
FXBWES2019000646	Miscellaneous finding	Paint peeling	112		No
FXBWES2019000648	Miscellaneous finding	Crack on wall	114		No

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXBWES201900064A	Tight seal on ceiling tiles		117	custodial	Yes
FXBWES201900064B	Miscellaneous finding	Peeling paint	111		No
FXBWES201900064D	Miscellaneous finding	Crack on wall	113		No
FXBWES201900064F	Miscellaneous finding	Wall crack	132		No
FXBWES2019000651	Miscellaneous finding	Wall crack	134		No
FXBWES2019000653	Tight seal on ceiling tiles		130	custodial	Yes
FXBWES2019000654	Uncomfortable temperature		Port 113	building	No
FXBWES2019000655	Tight seal on ceiling tiles	Hole in ceiling	Porta 126	custodial	Yes