

# Findings for walkthrough Long Reach High School: August 23rd, 2018 (WXMLRHS201800001B)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXLRHS2018000019	Visible mold on surfaces due to elevated relative humidity/dew point		Long Reach High School 232	environmental	Yes
FXLRHS201800001A	Uncomfortable temperature		Long Reach High School 232	building	Yes