

Findings for walkthrough Long Reach High School: August 23rd, 2018

(WXLRHS201800001B)

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|----------|----------------------------|---------------|--------|
| FXLRHS2018000019 | Visible mold on surfaces due to elevated relative humidity/dew point | | Long Reach High School 232 | environmental | Yes |
| FXLRHS201800001A | Uncomfortable temperature | | Long Reach High School 232 | building | Yes |