

# Findings for walkthrough Clarksville Middle School: February 25th, 2019 (WXXCMS201900014B)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXCMS2019000A12	Tight seal on ceiling tiles		Media	custodial	Yes
FXXCMS2019000A13	Tight seal on ceiling tiles		Media entrance	custodial	Yes
FXXCMS2019000A14	Floor coverings not level or secure (tile, carpets, wood board, etc.)		12a	building	No
FXXCMS2019000A15	Tight seal on ceiling tiles		12a	custodial	Yes
FXXCMS2019000A16	Floor coverings not level or secure (tile, carpets, wood board, etc.)		Earle	building	No
FXXCMS2019000A17	Miscellaneous finding	TV mounted too close to the sprinkler head	10		No
FXXCMS2019000A18	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		14	custodial	Yes
FXXCMS2019000A19	Floor coverings not level or secure (tile, carpets, wood board, etc.)		19	building	No
FXXCMS2019000A1A	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		19	custodial	Yes
FXXCMS2019000A1D	Tight seal on ceiling tiles	Post it note on the ceiling tile next to the stained ceiling tile says "roof".	54	custodial	Yes
FXXCMS2019000A1F	Elevated moisture per moisture meter		22	environmental	Yes
FXXCMS2019000A20	Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress		25	administration	Yes
FXXCMS2019000A21	Floor coverings not level or secure (tile, carpets, wood board, etc.)		Electrical room	building	No
FXXCMS2019000A22	Elevated moisture per moisture meter		26	environmental	Yes
FXXCMS2019000A23	Tight seal on ceiling tiles		26	custodial	Yes
FXXCMS2019000A24	Tight seal on ceiling tiles		hallway_64	custodial	Yes