

Findings for walkthrough Mayfield Woods Middle School: March 5th, 2019 (WXMWMS2019000166)

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|---|------------------|----------------|--------|
| FXMWMS2019000ADB | Tight seal on ceiling tiles | | cafeteria | custodial | Yes |
| FXMWMS2019000ADC | Elevated moisture per moisture meter | Blistering paint along exterior Windows | cafeteria | building | No |
| FXMWMS2019000ADD | General Cleanliness/Dust | Tops of microwaves dusty | 119 | custodial | Yes |
| FXMWMS2019000ADF | Plumbing fixture leaking/draining slowly | First sink leaking | 119 | building | No |
| FXMWMS2019000AE0 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | Custodial office | custodial | Yes |
| FXMWMS2019000AE2 | General Cleanliness/Dust | Under sinks dirty | 119 | custodial | Yes |
| FXMWMS2019000AE3 | Electrical wiring exposed or disconnected wires | Extension cord to backpack vac damaged | Custodial closet | administration | Yes |
| FXMWMS2019000AE5 | Tight seal on ceiling tiles | Stained ceiling tile | Custodial closet | custodial | Yes |
| FXMWMS2019000AE6 | Tight seal on ceiling tiles | Stained tile in back corner of the front nook | 119 | custodial | Yes |
| FXMWMS2019000AE7 | Floor coverings not level or secure (tile, carpets, wood board, etc.) | Floor plugs are popping up and are a tripping hazard | 119 | building | No |
| FXMWMS2019000AE8 | Tight seal on ceiling tiles | Food closet broken tile in far back and bowing next to the light. Stained tile next to light | 119 | custodial | Yes |
| FXMWMS2019000AE9 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | Kitchen | administration | Yes |
| FXMWMS2019000AEA | Tight seal on ceiling tiles | Tiles next to retractable wall hanging. Tiles dirty near vents and chalkboard. | 217 | custodial | Yes |
| FXMWMS2019000AEB | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dust on sills. | 217 | custodial | Yes |
| FXMWMS2019000AEC | General Cleanliness/Dust | Candy left in open, food on counters, open candy wrappers | Art closet | administration | Yes |
| FXMWMS2019000AED | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cord cover needed for projector. | 217 | administration | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------------|--|---|-----------------|--------------------|---------------|
| FXMWMS2019000AEF | Miscellaneous finding | Kuerig plugged in and on open sourced cell charger | Art closet | administration | Yes |
| FXMWMS2019000AF0 | Tight seal on ceiling tiles | Holes in a couple tiles | 218 | custodial | Yes |
| FXMWMS2019000AF1 | Tight seal on ceiling tiles | Tile around sprinkler broken in half | Storage | custodial | Yes |
| FXMWMS2019000AF2 | Tight seal on ceiling tiles | Stained near front door | 117 | custodial | Yes |
| FXMWMS2019000AF3 | Exterior doors not fully sealed (daylight) | | Cafeteria foyer | building | No |
| FXMWMS2019000AF4 | Tight seal on ceiling tiles | Broken along wall with window | 117 | custodial | Yes |
| FXMWMS2019000AF5 | General Cleanliness/Dust | Under sinks dusty | 117 | custodial | Yes |
| FXMWMS2019000AF6 | Tight seal on ceiling tiles | Tile outside 215 cracked. Dust on light fixtures especially near vents. | 216_hall | custodial | Yes |
| FXMWMS2019000AF7 | Tight seal on ceiling tiles | | 125 | custodial | Yes |
| FXMWMS2019000AF8 | General Cleanliness/Dust | | 125 | custodial | Yes |
| FXMWMS2019000AF9 | Tight seal on ceiling tiles | Ripped tile near sprinkler head | 219 | custodial | Yes |
| FXMWMS2019000AFA | Exterior doors not fully sealed (daylight) | Gaps under both doors larger on bottom left side | Lower stairwell | building | No |
| FXMWMS2019000AFB | General Cleanliness/Dust | Unsealed food | 125_closet | administration | Yes |
| FXMWMS2019000AFC | Electrical cords unsecured, extend across walkways, cord protectors not installed | Could use another cord cover for projector | 219 | administration | Yes |
| FXMWMS2019000AFD | Floor coverings not level or secure (tile, carpets, wood board, etc.) | Dust on baseboards | 219 | building | No |
| FXMWMS2019000AFE | Miscellaneous finding | Non-HCPSs hand sanitizer | 219 | administration | Yes |
| FXMWMS2019000AFF | Floor coverings not level or secure (tile, carpets, wood board, etc.) | Floor outlet missing cover in back of room | 116 | building | No |
| FXMWMS2019000B00 | Windows/Doors open | Window behind teachers desk seal coming loose | 219 | building | No |
| FXMWMS2019000B01 | Plumbing fixture leaking/draining slowly | Left sink dripping | Girls bathroom | building | No |
| FXMWMS2019000B02 | Miscellaneous finding | Mirrors scratched | Boys bathroom | | No |
| FXMWMS2019000B03 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dusty vents | 220 | custodial | Yes |
| FXMWMS2019000B04 | General Cleanliness/Dust | Dust on cabinets | 220 | custodial | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------------|--|--|------------------|--------------------|---------------|
| FXMWMS2019000B05 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cords are across floor by projector | 115 | administration | Yes |
| FXMWMS2019000B06 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cord covers for projector | 220 | administration | Yes |
| FXMWMS2019000B07 | Tight seal on ceiling tiles | Three tiles stained, one broken by right window | 115 | custodial | Yes |
| FXMWMS2019000B09 | Floor coverings not level or secure (tile, carpets, wood board, etc.) | Dust on floorboards | 220 | building | No |
| FXMWMS2019000B0A | Miscellaneous finding | See other hallway notes | 219_hall | | No |
| FXMWMS2019000B0B | General Cleanliness/Dust | Top of cabinet | 123 | custodial | Yes |
| FXMWMS2019000B0C | General Cleanliness/Dust | Dust and cob webs above exterior door | 122 | custodial | Yes |
| FXMWMS2019000B0D | General Cleanliness/Dust | Dust on floors and window sills | Stairway | custodial | Yes |
| FXMWMS2019000B0F | Tight seal on ceiling tiles | | Office | custodial | Yes |
| FXMWMS2019000B10 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cords exposed near middle desk | Teacher planning | administration | Yes |
| FXMWMS2019000B11 | Tight seal on ceiling tiles | Stained above door | S-3 | custodial | Yes |
| FXMWMS2019000B12 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | Main office | administration | Yes |
| FXMWMS2019000B13 | Tight seal on ceiling tiles | Cracked tile near front | C1 | custodial | Yes |
| FXMWMS2019000B14 | Tight seal on ceiling tiles | Cracked tile near door | 113 | custodial | Yes |
| FXMWMS2019000B15 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | | Workroom | administration | Yes |
| FXMWMS2019000B16 | General Cleanliness/Dust | Under sinks slightly dirty | 113 | custodial | Yes |
| FXMWMS2019000B17 | Elevated moisture per moisture meter | Under sink #3 water stain | 113 | environmental | Yes |
| FXMWMS2019000B18 | Tight seal on ceiling tiles | Stain in hall between health suite and workroom | Main office | custodial | Yes |
| FXMWMS2019000B19 | Tight seal on ceiling tiles | Ceiling tiles in small room hanging. Hanging tile in men's bathroom. | 224 | custodial | Yes |
| FXMWMS2019000B1A | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dusty | Workroom | administration | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|---|-----------------------|----------------|--------|
| FXMWMS2019000B1B | Elevated moisture per moisture meter | Sink #1 water stain underneath | 113 | environmental | Yes |
| FXMWMS2019000B1C | Tight seal on ceiling tiles | Lots of hanging tiles. | 224 | custodial | Yes |
| FXMWMS2019000B1D | Elevated moisture per moisture meter | Sink #2 water stain underneath | 113 | environmental | Yes |
| FXMWMS2019000B1E | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dusty | Health office | administration | Yes |
| FXMWMS2019000B1F | Miscellaneous finding | Soap only available at one out of seven sinks | 113 | administration | Yes |
| FXMWMS2019000B20 | Chemicals are capped | | Exam | administration | Yes |
| FXMWMS2019000B21 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dusty | Exam | administration | Yes |
| FXMWMS2019000B22 | General Cleanliness/Dust | Dust on shades | 224 | custodial | Yes |
| FXMWMS2019000B23 | Miscellaneous finding | No soap | Science preparation 2 | administration | Yes |
| FXMWMS2019000B24 | Plumbing fixture leaking/draining slowly | Dripping in sink | Science preparation 2 | building | No |
| FXMWMS2019000B25 | Tight seal on ceiling tiles | Stained above fridge | Science preparation 2 | custodial | Yes |
| FXMWMS2019000B26 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | CD player on counter | Science preparation 2 | administration | Yes |
| FXMWMS2019000B27 | Tight seal on ceiling tiles | Check ceiling tiles. Couple holes or hanging. Also check tiles in closet. | 221 | custodial | Yes |
| FXMWMS2019000B28 | Tight seal on ceiling tiles | Stained above pull down screen | 112 | custodial | Yes |
| FXMWMS2019000B29 | Tight seal on ceiling tiles | Stained near plug | 112 | custodial | Yes |
| FXMWMS2019000B2A | Tight seal on ceiling tiles | Stained near outside door | 112 | custodial | Yes |
| FXMWMS2019000B2B | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | Microwave | 213 | administration | Yes |
| FXMWMS2019000B2C | Tight seal on ceiling tiles | Stained above station 3 | 112 | custodial | Yes |
| FXMWMS2019000B2D | General Cleanliness/Dust | Sunflower seed shells and suntan lotion under sink #3 | 112 | custodial | Yes |
| FXMWMS2019000B2E | Miscellaneous finding | No soap available at sinks | 112 | administration | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|--|-------------------|----------------|--------|
| FXMWMS2019000B2F | Elevated moisture per moisture meter | Questionable. Crack in drywall bulkhead at entrance to related arts wing. Light bubbling of paint near crack | 123_hall | environmental | Yes |
| FXMWMS2019000B30 | Tight seal on ceiling tiles | Hanging tile in middle | 214 | custodial | Yes |
| FXMWMS2019000B31 | Plumbing fixture leaking/draining slowly | Faucet dripping | Staff women | building | No |
| FXMWMS2019000B32 | Tight seal on ceiling tiles | Stain | Custodial stoarge | custodial | Yes |
| FXMWMS2019000B33 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Phone cord sticks out. Phone charger wires showing. Heater non HCPSs | 214 | administration | Yes |
| FXMWMS2019000B34 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Yellow cord to pack back vacuum has wires coming out of sheating | Custodial stoarge | administration | Yes |
| FXMWMS2019000B35 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cord across walkway | 111 | administration | Yes |
| FXMWMS2019000B36 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dusty vents. | 214 | administration | Yes |
| FXMWMS2019000B37 | General Cleanliness/Dust | Food needs to be stored properly. | 225 | administration | Yes |
| FXMWMS2019000B38 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cord across front of walkway | 110 | administration | Yes |
| FXMWMS2019000B39 | Miscellaneous finding | See notes for added room | 218 | | No |
| FXMWMS2019000B3A | Miscellaneous finding | See notes for added room | 217 | | No |
| FXMWMS2019000B3B | Miscellaneous finding | See notes for added room | 216 | | No |
| FXMWMS2019000B3C | Miscellaneous finding | Scratched mirror on right | Boys room | | No |
| FXMWMS2019000B3D | Tight seal on ceiling tiles | Stain outside of s-5 closet | Hall | custodial | Yes |
| FXMWMS2019000B3E | Miscellaneous finding | Organize closet then dust. Needs bolts for shelves and more shelves. | S8 | | No |
| FXMWMS2019000B3F | Tight seal on ceiling tiles | Broken tile near back window | 108 | custodial | Yes |
| FXMWMS2019000B40 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Front cord not covered | 108 | administration | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|--|-----------------|----------------|--------|
| FXMWMS2019000B41 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dusty | 202_hall | administration | Yes |
| FXMWMS2019000B42 | Tight seal on ceiling tiles | Repair tag. Tile hanging. | 212 | custodial | Yes |
| FXMWMS2019000B43 | Tight seal on ceiling tiles | Tectum ceiling tile dirty from diffusers | 202_hall | custodial | Yes |
| FXMWMS2019000B44 | Exterior doors not fully sealed (daylight) | The left door underneath near middle has gap | Lower stairwell | building | No |
| FXMWMS2019000B45 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Needs cord covers | 212 | administration | Yes |
| FXMWMS2019000B46 | Tight seal on ceiling tiles | Cracked tile | s2 | custodial | Yes |
| FXMWMS2019000B47 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cords out | s2 | administration | Yes |
| FXMWMS2019000B48 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | Microwave | s2 | administration | Yes |
| FXMWMS2019000B49 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dusty vents | 211 | administration | Yes |
| FXMWMS2019000B4A | Floor coverings not level or secure (tile, carpets, wood board, etc.) | Dusty floors and floorboards | 211 | building | No |
| FXMWMS2019000B4B | Electrical cords unsecured, extend across walkways, cord protectors not installed | Needs cord covers for 2 cords. | 211 | administration | Yes |
| FXMWMS2019000B4C | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cords open in back of room | 107 | administration | Yes |
| FXMWMS2019000B4D | Miscellaneous finding | Near two outlets | 107 | administration | Yes |
| FXMWMS2019000B4E | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dusty vents and light fixtures | 212_hall | administration | Yes |
| FXMWMS2019000B4F | General Cleanliness/Dust | Dusty surfaces | 201 | custodial | Yes |
| FXMWMS2019000B50 | General Cleanliness/Dust | Dirty sink | Science closet | custodial | Yes |
| FXMWMS2019000B51 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | Microwave | Science closet | administration | Yes |
| FXMWMS2019000B52 | Exterior doors not fully sealed (daylight) | Connecting does not close correctly | 210 | building | No |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------------|--|---|--------------------|--------------------|---------------|
| FXMWMS2019000B53 | Tight seal on ceiling tiles | Cracked by projector | 106 | custodial | Yes |
| FXMWMS2019000B54 | General Cleanliness/Dust | Dusty surfaces | 202 | custodial | Yes |
| FXMWMS2019000B55 | Tight seal on ceiling tiles | Stained in front of classroom | 106 | custodial | Yes |
| FXMWMS2019000B56 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dusty | 202 | administration | Yes |
| FXMWMS2019000B57 | Excessive stuffed animals | Animals. Window curtains not school issued. Fabric around base of tables. | 202 | administration | Yes |
| FXMWMS2019000B58 | Floor coverings not level or secure (tile, carpets, wood board, etc.) | Floors cracked and damaged under window. | 210 | building | No |
| FXMWMS2019000B59 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cord coming from ceiling near science seminar 1 | 106 | administration | Yes |
| FXMWMS2019000B5A | General Cleanliness/Dust | Dusty | 210 | custodial | Yes |
| FXMWMS2019000B5C | Elevated moisture per moisture meter | Exhaust duct elbow right of stairs stained. Metal duct | Penthouse to ahu 3 | environmental | Yes |
| FXMWMS2019000B5D | Miscellaneous finding | Out of order stall | Girls bathroom | | No |
| FXMWMS2019000B5E | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cords open with surge protector | 106A | administration | Yes |
| FXMWMS2019000B5F | General Cleanliness/Dust | Dusty surfaces | 203 | custodial | Yes |
| FXMWMS2019000B60 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dusty | 203 | administration | Yes |
| FXMWMS2019000B61 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Needs cord covers | 209 | administration | Yes |
| FXMWMS2019000B62 | Miscellaneous finding | Plate doesn't fully cover hole in stall | Boys room | | No |
| FXMWMS2019000B63 | General Cleanliness/Dust | Dusty floor | S7 | custodial | Yes |
| FXMWMS2019000B64 | Tight seal on ceiling tiles | Tile above teachers desk hanging. | 209 | custodial | Yes |
| FXMWMS2019000B65 | General Cleanliness/Dust | Dusty surface | 204 | custodial | Yes |
| FXMWMS2019000B66 | General Cleanliness/Dust | Dust on window sill | 209 | custodial | Yes |
| FXMWMS2019000B67 | General Cleanliness/Dust | Dusty top of back bank of lockers | 204_hall | custodial | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------|--|--|---------------------|----------------|--------|
| FXMWMS2019000B68 | General Cleanliness/Dust | Dusty top of back bank of lockers | 204_hall | custodial | Yes |
| FXMWMS2019000B69 | Tight seal on ceiling tiles | Stained tile near back entrance | Media center | custodial | Yes |
| FXMWMS2019000B6A | Tight seal on ceiling tiles | Dust and check tiles | 209_hall | custodial | Yes |
| FXMWMS2019000B6B | General Cleanliness/Dust | Top of lockers outside of elevator dusty | 207_hall | custodial | Yes |
| FXMWMS2019000B6C | Tight seal on ceiling tiles | Tile near miss steeles office stained | Media center | custodial | Yes |
| FXMWMS2019000B6D | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cord cover | 208 | administration | Yes |
| FXMWMS2019000B6E | Plumbing fixture leaking/draining slowly | Leaky sink. | 208 | building | No |
| FXMWMS2019000B6F | Tight seal on ceiling tiles | Broken in back of room | Miss Steele | custodial | Yes |
| FXMWMS2019000B70 | Tight seal on ceiling tiles | Hanging tiles, possible water damage | 208 | custodial | Yes |
| FXMWMS2019000B71 | Excess dirt or moisture or obstructed or purposely placed obstruction indicating occupant distress | Dusty | 208 | custodial | Yes |
| FXMWMS2019000B72 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Need mat to cover cord | 207 | administration | Yes |
| FXMWMS2019000B73 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cord across doorway | Mr Grafton | administration | Yes |
| FXMWMS2019000B74 | Tight seal on ceiling tiles | Stained | Mr Grafton | custodial | Yes |
| FXMWMS2019000B75 | Appliances (toaster/coffee maker/fridge/space heaters/air cleaners other than HEPA) | Fridge and microwave | Dark room | administration | Yes |
| FXMWMS2019000B76 | Miscellaneous finding | Handrails loose, stained vent, stained floor | 7th grade stairwell | building | No |
| FXMWMS2019000B77 | Tight seal on ceiling tiles | Tile stained above guidance counselor | Hallway | custodial | Yes |
| FXMWMS2019000B78 | Electrical outlets not secured, cover missing, frayed wires on equipment | Lightbulb pink | Comm lab | building | No |
| FXMWMS2019000B79 | Tight seal on ceiling tiles | Left side | Guidance | custodial | Yes |
| FXMWMS2019000B7A | Tight seal on ceiling tiles | Tiles stained outside comm lab. | 214_hall | custodial | Yes |
| FXMWMS2019000B7B | Tight seal on ceiling tiles | Broken tile above elevator | 214_hall | custodial | Yes |

| Tracking Number | Finding Type | Comments | Location | Assigned To | Closed |
|------------------------|---|--|-----------------|--------------------|---------------|
| FXMWMS2019000B7C | Miscellaneous finding | Get rid of old items. Some stained used ceiling tiles and wood pallet with discoloration | Penthouse ahu2 | custodial | Yes |
| FXMWMS2019000B7D | Tight seal on ceiling tiles | Tile stained and ripped | 101 | custodial | Yes |
| FXMWMS2019000B7E | Tight seal on ceiling tiles | Stained ceiling tile | 102 | custodial | Yes |
| FXMWMS2019000B7F | General Cleanliness/Dust | Dust | 102 | custodial | Yes |
| FXMWMS2019000B80 | General Cleanliness/Dust | Dust and pencil sharpener shavings | Tp1 | custodial | Yes |
| FXMWMS2019000B81 | General Cleanliness/Dust | Dust | 103 | custodial | Yes |
| FXMWMS2019000B83 | General Cleanliness/Dust | Dirty floor dust | 104 | custodial | Yes |
| FXMWMS2019000B84 | Electrical cords unsecured, extend across walkways, cord protectors not installed | Cord across floor | 104 | administration | Yes |
| FXMWMS2019000B85 | General Cleanliness/Dust | Dust and dirty floors | 105 | custodial | Yes |