

# Findings for walkthrough Elkridge Elementary School: August 10th, 2018

## (WXXEES2018000037)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXEES201800002E	Visible mold on surfaces due to elevated relative humidity/dew point		Music Room (115) and Music Room Storage Closet	environmental	Yes