

Findings for walkthrough Glenelg High School: August 16th, 2018 (WXXGHS2018000039)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXGHS201800002B	Visible mold on surfaces due to elevated relative humidity/dew point		Kitchen Office	environmental	Yes