

Findings for walkthrough Glenelg High School: August 8th, 2018 (WXXGHS201800003B)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXGHS201800002A	Visible mold on surfaces due to elevated relative humidity/dew point		Room 139, 142, drama dressing rooms, and various rooms within wing containing rooms 99-112.	environmental	Yes