## Findings for walkthrough Atholton High School: February 25th, 2019 (WXXAHS2019000173)

Tracking NumberFinding TypeCommentsLocationAssigned To ClosedFXXAHS2019000BCAVisible mold on surfaces due to elevated relative humidity/dew pointDrama Stage Craft Work Area buildingYes