

# Findings for walkthrough Atholton High School: February 25th, 2019

## (WXXAHS2019000173)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXAHS2019000BCA	Visible mold on surfaces due to elevated relative humidity/dew point		Drama Stage Craft Work Area	building	Yes