Findings for walkthrough Elkridge Elemetary School: September 2nd, 2018 (WXXEES2018000043)

Tracking Number Finding Type Comments Location Assigned To Closed

FXXEES201800003C Visible mold on surfaces due to elevated relative humidity/dew point

Basement Level environmental Yes