

# Findings for walkthrough Hammond Elementary School: March 1st, 2019 (WXXHES201900019D)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXHES2019000FC6	Visible mold (leak)		Portable 13	environmental	Yes