

Findings for walkthrough Applications and Research Laboratory: September 18th, 2018 (WXXARL2018000051)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXARL201800008B	Plumbing fixture leaking/drainage slowly		B-37	building	Yes