

Findings for walkthrough Northfield Elementary School: August 22nd, 2018 (WXXNES2018000058)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXNES20180000C0	Visible mold on surfaces due to elevated relative humidity/dew point		144, 145, B11, and B13	environmental	Yes