

# Findings for walkthrough Homewood Center: October 17th, 2018 (WXXXHC201800005B)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXXXHC20180000E3	Visible mold on surfaces due to elevated relative humidity/dew point		Rear wall of the Portable/behind the building	administration	Yes