## Findings for walkthrough Homewood Center: October 17th, 2018 (WXXXHC201800005B)

Tracking Number Finding Type Comments Location Assigned To Closed

FXXXHC20180000E3 Visible mold on surfaces due to elevated relative humidity/dew point

Rear wall of the Portable/behind the building administration Yes