## Findings for walkthrough Talbott Springs Elementary School: November 13th, 2019 (WXTSES2019000251)

Tracking Number Finding Type Comments Location Assigned To Closed

FXTSES20190014C2 Visible mold on surfaces due to elevated relative humidity/dew point

3rd grade pod environmental Yes