

Findings for walkthrough Talbott Springs Elementary School: November 13th, 2019 (WXTSES2019000251)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXTSES20190014C2	Visible mold on surfaces due to elevated relative humidity/dew point		3rd grade pod	environmental	Yes