

# Findings for walkthrough Talbott Springs Elementary School: June 1st, 2019 (WXTSES2019000253)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXTSES20190014C4	Visible mold on surfaces due to elevated relative humidity/dew point		3rd Grade Pod	environmental	Yes