

Findings for walkthrough Running Brook Elementary School: November 15th, 2019

(WXRBS2019000258)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXRBES20190014ED	Plumbing fixture leaking/drainage slowly		1st & 2nd Grade Classrooms	building	Yes