

Findings for walkthrough Longfellow Elementary School: July 31st, 2019

(WXLOES2019000268)

Tracking Number	Finding Type	Comments	Location	Assigned To	Closed
FXLOES2019001637	Plumbing fixture leaking/drainage slowly		Office	environmental	Yes